Cons/ 40 47 REY. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 46N N. R. 12W		
•	Luce	COUNTY
DESCRIPTION OF CORNER $\frac{1}{4}$ corner between Secs. 21-	-28	
CORNER MONUMENT 1" pipe with 4" aluminum cap		
DATE MONUMENT PLACED AND WITHESSED6-11-69		
WITHESSES TO CORNER 4" Tamarack (LS NBT) S30	0°E 7.91	
5" B. Spruce (‡S NBT) We		
AND CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from one Tamarack witness tree, bearing S74°E, 43 links. Found log down and badly deteriorated, with face, scribe marks and calloused overgrowth. Found bottom of blaze on stump.

Found no evidence of use.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 7-25-69

REGISTERED LAND SURVEYOR