LUCE COUNTY REMONUMENTATION CORNER

APR 0 1 1996

For corners in

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Located in: Corner Code #	REGISTER OF DEEDS
(County)	Lber 2 Page 676
1. Public Land Survey T45N R12W K=1 \ Same T46N R12W	\ ___\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
TR TR	Kathy J. Mahar, Redister
2. Property Controlling S T R	REGISTER OF DEEDS
3. Miscellaneous STR	
Property in Sec. S TR	Register of Deeds Stamp & File Numbe
4. Lot No, Recorded Plat	
5. Private Claims	A B C D E F G H I J L I
	2 6 5 4 3 - 2 1
I, William L. Karr , in a field survey on Dec. 14 19 95 do hereby	state that under 4 7 8 9 10 11
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 conformance with regulations and rules therefore as required in the current manual of survey ins	structions of the
United States Department of the Interior, Bureau of Land Management or by a decree of a Court that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the rule of the rul	of the Michigan
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, recovered, found as expressed below:	8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	9 29 28 27 26 25
on this certificate.	11
	12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration	13
(K-1) Corner Common to Secs. 1 & 2, T45N, R12W and Secs. 35 & 36, T46N, R12W (K-13)	
1841: William A. Burt set post 12" Birch N56°E 51 links 28" Beech N85°W 23 links	
1849: Guy H. Carleton added two additional bearing t 14" Birch S45°W 13 links 12	rees, "Sugar S42°E 38 links
1978: Billy D. Buckler, P.S. 8887, recorded corner i	n Liber 1, Page 274 of corner
records. Found 1" iron bolt set by unknown su South of East-West fence. He added two new be	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
(K-1) This corner is being perpetuated as part program.	of the Luce County Remonumentation
Found both bearing trees as called for by Buckler	
position of a found 1" iron pipe with a 4" aluminum cap, found in place. Accepted corner position as found and added two new bearing trees. Added nails and tag to existing	
bearing trees.	CR COUNTY
	12/2- /2-
•	REJ LINE Z
C. Description of monument for corner and accessories established to perpetuate (K-1) Corner is a 1" iron pipe with a DNR 4" diameter.	
feet South of an East-West fenceline and 14 feet Wes	t of a woods road to the South:
Witnesses: 6" Sugar Maple N51°E	2.28'
12" White Ash (existing) S48°E 4" White Birch S40°W	4.01' 24.39'
12" Sugar Maple (existing) N72°W	8.37' WILLIAM L. WILLIAM L.
•	# KARR ** LAND **
1 0 1/	No. 3a.
Signed by William J. Ham	Date 12 26 95 27450 65
Surveyor's Michigan License No. 27450	LAND SUR
NOTE: Bearings are compass bearings corrected FORM AP	PROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28.
for declination. Distances are to a nail in side of	witness objects unless noted. REVISED MAY 14, REVISED JAN, REVISED OCT.
	METOLD DOLL