LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

	i iling nequirement of	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
For corners in	•			
Luce	Located In:	Corner Code #		
(County)	_ Located In:	Comer Code #		
1. Public Land Survey	T 47N R 9W		·	
2. Property Controlling in Section	T R S T R S T R R S T R R			
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number	
4. Lot No. , Re	corded Plat		ABCDEFGHIJK	L
5. Private Claims	Ш0	03/26/2008	2 6 5 4 3 2	_ -
. Charles I Conseleadei s		03/19/2008 do hereby state	3	+
above were in conformance with instructions of the United States a Court of Law and /or that the other rules of the Michigan Boar	74, Michigan P.A. of 1970, the corregulations and rules therefore as r Department of the Interior, Bureau corner points mentioned in lines 3, od of Land Surveyors or by a De	rner points mentioned in lines 1 and equired in the current manual of surve of Land Management or by a decree 4 and 5 above were in conformance will be cree of a Court of Law; established	rey 5	-13-
re-established, monumented, recov	ered, found as expressed below:		9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	75
NOTE: Not more than 2 corr	ners, all in the same town and re	ange, may be recorded	10 30 29 27 26 11	
on this certificate.			12 31 32 33 34 35	-36-
			13	!
A. Description of original n	nonument and accessories and	I/or subsequent restoration:		
(H9) Quarter corner of midway and on line be 6 links, 5" Tamarack	etween Section corners.	and 27. 1965 - Frank J. . Set 1"ID I.pipe with a	Bray RLS reestablished the corne 4" aluminum cap. 7" Tamarack S56	er 6W
(G10) Quarter corner midway and on line bolinks, 7" J.Pine N70	etween Section corners	and 28. 1965 - Frank J . Set 1"I.pipe with 4"	. Bray RLS reestablished the cor aluminum cap. 5" Tamarack S87W :	ner 3.5
R Description of corner ev	idence found and/or method	applied in restoring or reestabli	ishing corner:	
(H9) Recovered the 19	965 monument in good co BTs were recovered in a	ondition and S23W 0.47'	from the midway position intender ecord bearing and distance. the position of the original	d
SW, in good conditions snow. The monument	n. The NBT J. Pine N⊱ is N19E 1.4' from the (was not recovered. Its	ring and distance from the 1965 N s remains may be obscured by deep d in 1965 and I accept same as a nal corner.	вт
C. Description of monume	nt for corner and accessories	established to perpetuate locati	ing the position of the corner:	
(H9) Found 1"ID I.pi Set measuring nail w 7" Tamarack S75E 24. 9" Tamarack S56W 4.1 5" Tamarack N36E 4.6 9" Tamarack N37W 29. Bearings are magneti	do do mrkd "1/4S NBT" 55' do	•	S86W 2.6' old blazes 1965 NBT S58E 6.95' mrkd "1/4S NBT" N30E 20.4' do	ip. of:
Signed by	· 1/	Date Date 1986 al Resources, Office of Land and Fac	09/08/2008 STEPHAN J. SZYSZKOSKI LAND SURVEYOR No.	***

47099 47100 FORM APPROVED BY MICHIGAN STATE BOARD OF

4 A N D Revised by 14, 1975 Statistised Jan., 1983 Rervised Oct., 1995