

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T46-47 NR 10 W ..

Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner for Sections 3-34

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 10" Cedar N82°E 10 Links

Marked "1/4S NBT"

11" Cedar S23°W 15 1/2 Links

Marked "1/4S NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Replaced at site of Tamarack Corner tree stump.

Found Cedar B.T. bearing N40°W 13 links. Stump in poor condition.
B.T. very plain.

Corner found by J. Kutchera, Ass't. District Forester and L. Rubick, Aide.

Corner lies 3/4 chain South of County Road.

Corner placed and witnessed May 7, 1958.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 12/4/58
REGISTERED LAND SURVEYOR