

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47. NR. 10-11 W.

_____ L. n. e. _____ COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 36 and 31 _____

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap _____

WITNESSES TO CORNER 13" Red Pipe (1/4s NBT) N 54° W 155 Links _____

7" B. Cherry (NBT) S 79° E 76 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established 50 links to west of old fence corner. Fence appears to have been built with an allowance for a road along the section line to south and on east-west quarter line.

Corner was placed and witnessed May 11, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 5/23/60
REGISTERED LAND SURVEYOR
Billy D. Buckler