LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Luce	Located in:	Corner Code ≠#		
(County)				
1. Public Land Survey	T 47H R 10H			
	<u>' — " — </u>			
	T R			

Property Controlling in Section
 Miscellaneous

Property in Sec.

Register of Deeds Stamp & File Number

4.	Lot No ,	Recorded Plat	
5	Private Claims		

I, Stephan J. Szyszkoski , in a field survey on June 07, 1995 , 19 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Lew and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

			-				_	•••				
2	Ĺ			,			ĹÏ	<u></u>	\Box			
3		<u> </u>		_		_		lacksquare		\vdash		Ц
٠	\vdash	}_	-	-	1	<u> </u>	<u> </u>	<u> </u>	ار ا	<u>'</u> -	<u>ا</u>	2_
	_	\vdash	_	Н	_	\vdash		H	Н			Н
,	Ī	•— 	Ī	<u>, </u>	Ī		Ī	5	1	ا	[]	3—
	_;	ľ	_2	ľ	2	Ĭ	Ĩ			3—	_;	_
١	_		_	-				Н	\sqcup	<u> </u>	-	Н
9	—з	_6_	—2	-	—2	.	⊢ ?	<u>'</u> -	—2	•	<u> </u>	5_
			_			_			_			_
		Ï	— 3	j			-3	_		• 		,

A. Description of original monument and accessories and/or subsequent restoration:

(81) Quarter corner common to Section 6 T47M-R10M and Section 31 T48M-R10M. Corner reestablished in 1964 by Frank J. Bray, RLS, by single proportionate measurement between adjacent Section corners. Bray placed a 1" iron pipe with a 4" aluminum cap and the following witnesses: 10" Y. Pine S37E 19 links, 6" M. Pine M43E 35.5 links. Found no subsequent record.

(2-Sec. 6) East 1/16 corner between Section 6 T47M-R10M and Section 31 T48M-R10M. Corner not established in the original survey. Corner established by Frank J. Bray, RLS, in 1964, midway between Section corner to east and 1/4 corner to west. Bray placed a 1° iron pipe with 4° aluminum cap and the following witnesses: 9° W. Pine S85E 27 links, 10° M. Pine Morth 51 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(B1) Found and accepted Bray's monument, as described, in good condition, at record bearing and distance from the remaining W. Pine witness. The Y. Pine witness is gone. Remarked the top blaze on the White Pine and marked three new accessories as described below. (2-Sec. 6) Found Bray's monument as described, in good condition, at record bearing and distance from his W. Pine accessories, both in good condition. Remarked the top blaze on the 1964 witnesses and placed measuring nails in them. Marked two new bearing trees as described below.

٠.	Description	n or monument for	corner and aci	Cessones esta	iblished to per	pervare locating	the position of the comer:
í	ll' Found I"	oine with 4° cap.	ť	(2) Found 1"	nion with 4 a	ຂໍໄນຫ່ານຫຼວຂາ	

Blazed, scribed, and set measuring nails in the following bearing trees: in the 10" W. Pine M43E 23.65" (1964 witness) 12" W. Pine SBOE 23.35" "1/4S MBT" 14" W 6" Spruce M62W 19.25" "1/4S MBT" 8" Ce 5" Maple SBIW 6.6" "1/4S MBT" 8" Ma found an old 5" squared and scribed cedar post adjacent. Bearings are

magnetic.

Blazed, scribed, and set measuring nails in the following:

12° M. Pine SBSE 18.0' (1964 tree)

14" N. Pine Boot 133.5" (1964 tree)
8" Cedar M15N 5.7" "E1/16 BT"
8" Maple S78N 3.4" "E1/16 BT"
8 earings are magnetic.

STEPHAN J. SZYSZKOSKI LAND STIRVEYOR No. 33986

Signed by Stephen J. Sayankoli Date 8/28/95
Surveyor's Michigan License No. 33986