LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

Two Corners.

FOR CORNERS OF	-: LGCATED IN-:	CORNER CODE NUMBER	
i. PUBLIC LAND	SURVEY T. 47X., R. 11	x. J-11	İ
2. PROPERTY CO	NTROLL 12 T. 47 S., R. 11	x 16-Sec.12	
4. LOT NO	, RECORDED PLAT		
5, PRIVATE CL A I	MS		REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner point, field survey on restored as expressored survey instructions of law.	do hereby constraints and 2 above 1974, establices below and in conformance with citions of the United States Department Furthermore, that the corner point 19, found, recovered, restorate rules of the Michigan State Board	(identified with circles on index ished, re-established, monumente regulations and rules therefore a at of the Interior, Bureau of Land is mentioned in lines 3,4 and 5 red, established or re-established	code diagram—over) were, in a ed, re-monumented, recovered or s required in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in con-
A. Description o	f original monument and accessories Quarter Corner bet. Sec's 2 Bearings were: Hemlock 14"	6-35, set by Geo H. Cann	on D.S. in 1853. emlock 14". N76°E, 16 1k
16-Sec.12	East 1/16 corner on south s	ide, Sec. 12.	
B. Description o	f corner evidence found and/or metho Corner re-established mi	d applied in restoring or re-estab dway and on line bet. tw	olishing corner: o Sec. Corners.
16-Sec.12	Corner placed midway bet	ween Sec. Cor to East an	d ¼ Corner to West.
C. Description of Placed 1" J-11 16-Sec.12		at both corners. ne, S50 ⁰ W, 92.41 and 8"	W. Pine, S64 E, 74.41
SIGNED BYSURVEYOR'S M	Billy D. Buckler ICHIGAN REGISTRATION NO 88	- DATE <mark>6-5-7</mark>	4 CO SURVEY OR SURVEY OR NO.
FOR STATE AN	D UNITED STATES AGENCIES:		
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	
APPROVED AND	O SIGNED BY MICHIGAN REGISTER	RED LAND SURVEYOR DATE	(SEAL)

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION (1989) 28 (1991) AND THE BOARD OF REGISTRATION (1989) AND THE STATE BOARD OF REGISTRATION (1989) AND THE STATE BOARD O

SURVEYOR'S MICHIGAN REGISTRATION NO. ______ -

19. No. MCM735 19. South Course Harmand American