LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH: P.A.1970 Luce Co.

| 1. PUBLIC LAND SURVEY T. 48 N. R. 8 V. 2. PROPERTY CONTROLL. ING. IN SECTION. T. S. R. V. 3. MISCELLANEOUS PROPERTY IN SECTION T. N. R. R. V. 4. LOT NO. RECORDED PLAT 1. Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in field survey on 1972, established, re-established, monumented, re-monumented, recovered restored as expressed below and in conformance with regulations and rules therefore as required in the current manus of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above ere, in a field survey of 1972 in found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court law: Sec. Cor. 9-10-15-16, originally placed by Wells Burt., D.S. 1850. Bearings were: Sugar 10" N88°W 38 Links Sugar 7" S72°E 40 Links B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found 6" Concrete Post, set by Luce Co. Rd. Commission. |
|--|
| 2. PROPERTY CONTROLL. ING IN SECTION. 3. MISCELLANEOUS PROPERTY IN SECTION. 7. S. R. 8. PRIVATE CLAIMS 1. Billy D. Buckler 1. do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram — over) were, in field survey on 1972. established, re-established, monumented, re-monumented, recovered, recovered as expressed below and in conformance with regulations and rules therefore as required in the current manus of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 and were, in a field survey of 19. found, recovered, restored, established or re-established as expressed below and in corformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law: 8. Description of original monument and accessories and/or subsequent restoration: 9. Sec. Cor. 9-10-15-16, originally placed by Wells Burt., D.S. 1850. 8. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found 6 ⁿ Concrete Post, set by Luce Co. Rd. Commission. |
| 3. MISCELLANEOUS PROPERTY IN SECTION T. S. R. V. Luce County Reg. of Deeds 4. LOT NO. RECORDED PLAT 1. Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in field survey on 1972, established, re-established, monumented, re-monumented, recovered as expressed below and in conformance with regulations and rules therefore as required in the current manus of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey of formance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court. In the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court. Post of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court. Bearings were: Sugar 10" N88°W 38 Links Sugar 7" S72°E 40 Links B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found 6" Concrete Post, set by Luce Co. Rd. Commission. |
| S. PRIVATE CLAIMS do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in field survey on 1972, established, re-established, monumented, re-monumented, recovered as expressed below and in conformance with regulations and rules therefore as required in the current manus of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of court of law. Furthermore, that the corner points mentioned in lines 3,4 and 3 above were, in a field survey of the found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of the Sec. Cor. 9-10-15-16, originally placed by Wells Burt., D.S. 1850. Bearings were: Sugar 10 ⁿ N88 ^o w 38 Links Sugar 7 ⁿ S72 ^o E 40 Links B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found 6 ⁿ Concrete Post, set by Luce Co. Rd. Commission. |
| I. Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram over) were, in field survey on |
| the corner points mentioned in lines 1 and 2 above (identified with circles on incircles on the corner points mentioned in lines 1 and 2 above (identified with circles on incircles on inc |
| Bearings were: Sugar 10" N88°W 38 Links Sugar 7" S72°E 40 Links B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found 6" Concrete Post, set by Luce Co. Rd. Commission. |
| Sugar 10" N88°W 38 Links Sugar 7" S72°E 40 Links B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found 6" Concrete Post, set by Luce Co. Rd. Commission. |
| B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found 6 ⁿ Concrete Post, set by Luce Co. Rd. Commission. |
| Found 6" Concrete Post, set by Luce Co. Rd. Commission. |
| |
| C. Description of monument for corner and accessories established to perpetuate locating the position of the corner Re-witnessed Corner as perpetuated by Road Commission. |
| New Bearings: R. Pine 6" \$56°W 25.1' R. Pine 8" \$25°W 47.0' |
| SIGNED BY Billy 4. Buckler DATE 6/20/72 |
| DATE DATE |
| 8887 |
| 8887 |
| SURVEYOR'S MICHIGAN REGISTRATION NO |
| SURVEYOR'S MICHIGAN REGISTRATION NO |

<u>.</u>

AND THE PROPERTY OF

Form No. ML M735 DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.