CONS. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

	T. 48 N.R. 8-90 Luce Count
DESCRIPTION OF CORNER _	Corner between Secs, 1-6.
CORNER MONUMENT	l" pipe with 4" aluminum cap.
DATE MONUMENT PLACED AN	D WITNESSED
WITHESSES TO CORNER	00 a (1a xmm) ado0t. 20 ft
CIRCLE CORNER REGISTERED	AND TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.
	This corner replaced at wood post set by H. Lawrence, R.L.S. Found remains of one tamarack bearing tree; a stump in poor condition.
	This corner replaced at wood post set by H. Lawrence, R.L.S. Found remains of one tamarack bearing tree; a stump in poor
	This corner replaced at wood post set by H. Lawrence, R.L.S. Found remains of one tamarack bearing tree; a stump in poor condition. Corner lies 1 3/4 chains south of stream in a thick tag alder
	This corner replaced at wood post set by H. Lawrence, R.L.S. Found remains of one tamarack bearing tree; a stump in poor condition. Corner lies 1 3/4 chains south of stream in a thick tag alder flat.