MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

SIGNED

This corner replaced from one possible B.T.; a down W. Pine in poor condition, bearing, S40°E, 34 lks.
Found no identifying marks but this is the only W. Pine near. Distance checks to cor. ½ mile east.
Corner lies 30° north of road.

SURVEYOR'S SEAL

Billy D. Buckler DATE 9-21-70