## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION



## LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced in intersection of fire lanes.
Pipe placed by Marcus Schaaf, R.L.S. has apparently been removed by vehicle traffic.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

SIGNED Billy D. Buckler DATE 8-31-70

REGISTERED LAND SURVEYOR