## MICHIGAN DEPARTMENT OF CONSERVATION

## FORESTRY DIVISION

## LAND CORNER RECORD

T 49 NR 10 W T 49 NR 11 W

			<b></b>
DESCRIPTION	OF	CORNER	Meander Corner between Sections 1 & 6
DESCRIPTION	OF	CORNER	MONUMENT_1" Pipe with 4" Brass cap
WITTNESSES	то	CORNER	_ 6" CederN_ 20_F 44_ Links
			6* Cedar - N 50 F - 35 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was pointed out to me by B. McTiver, District Forester, of Newberry. Two original B.T.'s still in place, poor condition.

Corner was placed and witnessed May 6, 1952.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 3/23/53