LAND CORNER RECORDATION CERTIFICATE

	Filing Requirement of Ac	t 74, Mich. P.A. 1970 as Am	ended								
For corners in							•				
Luce	Located In:	Corner Code #									
(County)	_ Located III.	Corner Code #									
1 Dublic Land Curvou	T 401 P 4011	00									
1. Public Land Survey	T 49N R 12W	<u> </u>									
	TR										
2. Property Controlling	S T R										
in Section	S T R										
3. Miscellaneous	s T R					-					
Property in Sec.	S T R										
_			Re	gister	of Deed	s Stam	p & File	Nun	nber	г	
4. Lot No. , Red 5. Private Claims	corded Plat		1 7	3 C	DE	F G	H	I (7_1	K 1	<u>L</u>
J. Private Claims			2	<u>-</u>	- ┇┷┼	- 4	ş	 	ļ —	_	ļ_
Chamban I Canadanii	n a field survey on 01/13/2	2010 da hawahii ataba	3		┦╼╂╌	-	-	-	_	╀	┝
i, Stephan J. Szyszkoski, ir	74, Michigan P.A. of 1970, the corner		34 -	-	·	- 9	10	1-1		┼1	3-
above were in conformance with a	regulations and rules therefore as requi	red in the current manual of surve	, s	-		+	\dashv	╁	-	╂	┢
instructions of the United States I	Department of the Interior, Bureau of L	and Management or by a decree of	of 6 -1	 -	-1/2	16-	15	 1	4	3	3
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with					╅	+-1		\vdash	 	 	
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established re-established, monumented, recovered, found as expressed below:			^{1,} 8 —1	9	20-	-23	2'2 _	1-2	3 	1-2	i4
re-established, monumented, recove	ered, found as expressed below.		9		 	19			<u> </u>	\vdash	<u> </u>
NOTE: Not more than 2 corn	ners, all in the same town and range	e. may be recorded	10 3		29-1-	-28	27 	2	5 	2	5
on this certificate.	iers, all in the same town and range	,,, 22 / 2201 1111	11				7,		_	Ι,	16-
on this certificate.			12 3		Ĭ		Ĭ				Ĺ
A Description of original m	nonument and accessories and/or	subsequent restoration:		1							
	o Sections 21-22-27-28. N72E 29 links, W.Birch 8		Franc	is Co	lman	Depu	ty Su	rve	yor	•	
B. Description of corner evi	idence found and/or method app	lied in restoring or reestablis	hing co	rner:							
original corner on the	st and accessories were no ne ground. Reestablished rd between monumented cor 0.11' south (80.65 ch. GLO	the corner position b ners 2649.69' north (4	y dou 10.325	ble p ch.	ropor GLO),	tion: 530	ate m	eası	ure	the men	! ! t
(G9) Set 1"IDx36" I.p	it for corner and accessories estal pipe with 4" alum. MDNR ca ith MDNR tag in the side o	ap.	g the p	osition	of the	corne F M	er:				
10" Spruce S28W 5.64' 10" Maple N44W 7.28' 12" Maple N27E 30.42' 6" Maple N86E 28.57' Bearings are magnetic	mrkd "S28 NBT" "S21 NBT" "S22 NBT" "S22 NBT"		;		L	PHANSZKO: AND VEYO					

Signed by

33986 Surveyor's Michigan License No.

Date

03/22/2010

For the Michigan Department of Natural Resources and Environment, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971