LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce (County)	Located In:	Corner Code #						
1. Public Land Survey	TR							
2. Property Controlling in Section	S 27 T 49N R 12W S 28 T 49N R 12W S T R	10 5						
3. Miscellaneous Property in Sec.	S T R R	· · · · · · · · · · · · · · · · · · ·	Rea	ister of D	eeds Sta	mp & File	Number	r
4. Lot No. Re 5. Private Claims	corded Plat		1 A B	C D	E F	G H	I J 1	K L M
	10 12/	08/2009	2 - 6-	─ - - - - - - - - - - - - - - - - - - -	┼	 	<u>├</u> -}	╆┼┪
ı, Stephan J. Szyszkoski , i	n a field survey on 55	08/2009 do hereby state				10-		
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2					<u> </u>		1	
above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6				12-	16-	1.5	_1+_	13-
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7								
	d of Land Surveyors or by a Decree	of a Court of Law; established,	819-	20		-22-	23_	-24-
re-established, monumented, recov	vered, found as expressed below:		9		+			
NOTE: Not more than 2 corron this certificate.	ners, all in the same town and range	, may be recorded	10 -30- 11 -1 12 -31-	32_	28- 	27	26 	-25- -36-
A. Description of original m	nonument and accessories and/or	subsequent restoration:	13	<u> </u>			lL	

- (10-Sec. 27) South 1/16 corner between Sections 27 and 28. Not established in the original survey.
- (5-Sec. 28) North 1/16 corner, Section 28. Not established in the original survey.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (10-Sec. 27) Established the corner midway and on the Section line between Quarter corner 1324.78' north and Section corner 1324.78' south.
- (5-Sec. 28) Established the corner midway and on a straight line between Quarter corner 1329.73' north and the intersection of 1/4 lines of Section 28 1329.73' south.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- (10) Set 1"IDx36" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 16" Maple S84W 46.8' mrkd "S1/16 BT" do 11" Maple S03W 44.5' 18" Y.Birch S63E 19.75' do 14" Maple S88E 30.58' do Bearings are magnetic.
- (5) Set 1"IDx36" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 20" Maple S41W 18.44' mrkd "N1/16 BT"

6" Maple NO9W 29.16' do

6" Maple N18E 24.17' do

12" twin Maple S68E 19.81'

Bearings are magnetic.

Surveyor's Michigan License No.

03/22/2010

SZYSZKQSKI For the Michigan Department of Natural Resources and Environment, Office of Land and

LAND IRVEYOR

d # A

STEPHAN J

47323

14, 1975