## LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Require	ement of Act 74, Mich. P.A. 19	970	R T
Livingston		0 0.1 1/	V Z	æ ?
(County)	Located In:	Corner Code ##	[65]	N.C. 7
Public Land Survey	T 2N R 3E	M-11	40n	TEILED
T. Public Land Survey	T R		84°C	
	T R			
	T R		<u>ئىخ</u> ئ <del>ىخ</del> دا	₩ · · · · · · · · · · · · · · · · · · ·
2. Property Controlling in Section			L.S.C.# 80m	ຶ
3. Miscellaneous	S T R S T R		Register of Deeds St	tamn & File Number
Property in Sec.	S R		megister of Deeds Of	amp a the Humber
7 . 1 -1 M -	Daniel Dist			
	Recorded Plat		A B C D E	F G H I J K L M
			2 6 5	-43211
•			3	
L Darroll D. Higher	_ , in a field survey on Decem	her 17. 10 93	5	- 9 - 10 - 11 - 12 - 12 - 12 - 12 - 12 - 12
do hereby certify that under r	equirements of P.A. 74, Michigan P.A.	of 1970, the corner points mentioned	6 10 17	16 16 1413
	in conformance with regulations and tructions of the United States Depart			
Management or by a decree of	of a Court of Law and/or that the corne	r points mentioned in lines 3, 4 and 5	8 19 20 1	_21222324
above were in conformance v	with the rules of the Michigan Board o re-established, monumented, re-m	f Land Surveyors or by a Decree of a nonumented, recovered, found as	9	
expressed below:	To colubration, manamemos, to the		103029	28272625
	corners, all in the same town an	d range, may be recorded	11	
on this certificate	9.		12 31 32	-3 <sup>3</sup> 3 <sup>4</sup> 3 <sup>5</sup> 3 <sup>6</sup>
A. Description of origina	I monument and accessories and	/or subsequent restoration:		
GLO: 1825				
	16" N71W 72 lks. 18" S79W 150 lks.		6 9 may 2 8 7 4 V	
Aspen	10 3/9W 190 1K3.	·		1993
				V
			007	WMISSION
B. Description of corner	onal historical inf evidence found and/or method a rod l'east of cen	pplied in restoring or reestablish	hing corner:	
		,		
			•	
		.0		
C. Description of monum	ent for corner and accessories e	stablished to perpetuate locatin	g the position of the o	corner:
Monumentation faithful reconstruction of the contract of the c	ked with 2" dia. on Corner, P.S. 3 establishment of the .11' SET NAIL/TAG W/	19834, and is accepted position of the orange of the orang	stamped "Liv pted as a	ringston Co. careful and
005 DEG. 64				N. Bray
Signed by	ull 46 A	pproved by Liv. Co.	Peer Group:	Nov. 17, 1993
Surveyor's Michigan Licen	se No. 19834		ADDONUES BY MICHIGAN STATE SO	ARD OF LAND SURVEYORS, JAN. 28. 1971
ourreyor o mionigan Licen		FORM	AFFRUYED OF MICHIGAN STATE BUI	REVISED MAY 14, 1975 REVISED JAN., 1983

IOSCO TOWNSHIP, T2N, R3E

M-11, NORTHEAST CORNER SECTION 36

FIELD 11-06-1993 D.D. HUGHES AND ASSOCIATES

- Found 1/2" iron rod 1' east of centerline Dutcher Rd., 0.1' below grade, 36.80' south found 1/2" iron rod for A-11, Marion, Twp. North 64.00' fd. 1/2" iron rod.
- 1825. corner first set by Sylvester Sibley, Deputy U.S. Surveyor. Later falling for A-11, Marion shows 56 links (36.96' south)
- 1861, Ezra Fairchilds, subdivides Section 36, shows 1/4 line measure.
- 1878, Isaac Teller, County Surveyor subdivides Sec. 30, Marion, sets A-9 and A-11 "....located by closing distance to Iosco Twp. Sec. 36"
- 1915, Grant Dunning shows falling distance as 56 links (36.96').
- 1918, Grant Dunning subdivides Sec. 36, Iosco Twp., "....set Northeast corner 80.19 chains north of Southeast corner."
- 1963, Charles Garlock sets 1/2" X 16" iron at fence line West for NE corner Sec. 36.
- 1971, Henderson and Bates shows closing distance of 100.8' in survey of Section 30, Marion for Detroit Edison. Set SW of Sec. 30, Marion. Found SE 25, Iosco.
- 1976, Oscar Boss, "...set 1/2" iron on line with NW corner and West 1/4 corner Section 31, Marion, 36.96' North of the West 1/4 corner (government deflection)" Files Act 74, LSC no. 948.
- 1986, Garlock uses Boss corner for NE Sec 36.
- 1990, Matthew Brady uses same corner, sets new witness'
- 64 feet north of this point is an iron set by Garlock and used by Benton and Henderson and Bates at occupation line to West. Most surveyors are not using this point now.