4144	MONUMENTATION CORNER	·		.x015 Of 1570	
		R RECORDATION CEI			19
For corners in LIVINGSTON		ement of Act 74, Mich.	. P.A. 1970	Nov 10 NANC REGIST LIVINGST	Alex 3
(County)	Located In:	Corner Code ##		must sent on a	T
Public Land Survey	T R T R T R	G-12		8 15 AH Y HAVILAND ER OF DEET ON COUNTY 48843	FILED
	T R	710-16		S S S S S S S S S S S S S S S S S S S	
2. Property Controlling S	S T R		L.S.C.#284m	- American	-
in Section S 3. Miscellaneous S	S T R S T R				
	S T R		Register of D	eeds Stamp & File	Number
4. Lot No, Reco	arded Dist				
5. Private Claims			A B	CDEFGH	IJKL)
			2 - 6-	53	
			3		
Donald G. Richay	rds a sield survey onSepter	mber 28th	4	- 8 910 	11-1-12-
do hereby certify that under require	ements of P.A. 74, Michigan P.A.	of 1970, the corner points me	entioned 6		
in tines 1 and 2 above were in co			ed in the	17-16-15-	13-
Management or by a decree of a Co	ourt of Law and/or that the corner	r points mentioned in lines 3	,4 and 5 819	202122	2324
above were in conformance with th Court of Law; established, re-es				1111	
expressed below:	owniented, mondinented, re-n		10 30-	29 28 27	2625
NOTE: Not more than 4 corn	ers, all in the same town an	d range, may be recorde	1 1.		++++
on this certificate.	,		12 -31- 13 -1-	32 33 34	35 36-
mile post a White Oal a White Oal	Sections 33 & 34 40. k 16 N 5 W 13 k 16 S 43 E 36" y, June 13th, 1823	oo (charns) set n	all-		
	north/south fence 1:	ine			
(see reverse side i	for research and inv	estigation summary		A STATE OF THE PARTY OF THE PAR	Man.
			•	THE DOWN	E STORY
			Š	DONALD G. RICHARD LAND SURVEYOR No. 24614	N. S. S.
		•		& G. RICHARD)S 🕻 🛪 🐉
				LAND SURVEYOR	
				No.	10 %
			i i i i i i i i i i i i i i i i i i i	24614	10 July 25 July 20 Jul
				CHAIC	0 a
	•			A Salar Se Marie Se Marie	
Description of monument f	or corner and accessories e	stablished to perpetuate	tocating the position	of the corner:	
·	iron pipe w/brass ca				
Corner" and "PS 24	614"	. "	·		
	/tag* in north side /tag* in northwest s				
	/tag* in northwest s 'tag* in west side 20				
	ag* in north side 15				
Stage road Withday	ston County Survey V	Jitnese" and are	-		
stamped "24614"	Scor county survey		Capproved by per	on anoun 10 10	0.6.3

DONALD G. RICHARDS

∎urveyor's Michigan License No.

24614

≣gned by .

PA. 345 1980, APPROVED BY LIVINGSTON COUNTY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

PEER GROUP ON 1960, SEP 460, REP 460, REP 460, 1983

Date October 20, 1994

COHOCTAH G-12

Deputy Surveyor Sylvester Sibley set a wood post to mark this quarter corner on June 13th, 1823. County Surveyors records dating to 1893 provide a witness for this point but fail to identify the corner material.

This corner is depicted on a 1944 survey by Clay Gordon which shows it as lying an exact 2640' north of the SW corner of Section 34. The material marking the corner, however, is not identified on Gordon's survey.

Some thirty years later, Karol R. Piotrowski set an iron to mark this corner, stating that he "set iron at intersection of fences" and providing one witness paraphrased as north 110' to a property corner. This distance is consistent with Gordon's survey of 1944.

More recently, in 1988 Darrell D. Hughes performed a survey in Section 33 and provides four new witnesses for this quarter corner, and confirms Piotrowski's witness from 1974.

On September 28th, 1994, fieldcrews recovered this point as a 1/2" iron on a north/south fence line. All four of Hughes witnesses from 1988 were recovered and at a distance of 110' to the north, an iron rod at a fence corner was recovered.

The distances observed from this quarter corner to corner G-11 checked within 4 inches of the same line as reported by Hughes in 1988. To the south there is a minor discrepancy. The length of the line from G-12 to G-13 was recorded as 2654.46 by Benton in 1974, and 2654.28 by Hughes in 1988. However, a Clay Gordon survey from 1944 records this distance as exactly 2640.00. Our observed distance for this line was within 0.01' of the distance recorded on Benton's survey, and we suppose that Gordon's exact 40 chain measure for this line is either an error in compiling the drawing or was meant to record the GLO measure for the line.

Donald G. Richards, PS 24614 October 4, 1994 approved October 19, 1994