REMONUMENTATION

MAR 1 3 1998

MACKINAC COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE

SECTION			
	Filing Requirement of Act 74, Mich. P.A. 1970		
For corners in	,		

	Mackinac (County)	Located In;	Corner Code ##	accived a fill		
1.	Public Land Survey	T <u>40N</u> R <u>4W</u> T R T R T R	L-3 ½ Cor common to Sec's 1 & 12	DIANE FRANKOVICH MACYNIC DE NIVERGISTEL OF DEEDS DEC 29 1997 AM PM		
2.	Property Controlling in Section	S T R S T R		7/8/9/10/22/1/2/3/4/5/6		
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number		
		Recorded Plat		A B C D E F G H I J K L		
do in cu Ma ab Co ex	hereby certify that under rec lines 1 and 2 above were in rrent manual of survey instranagement or by a decree of ove were in conformance with ourt of Law; established, in pressed below:	, in a field survey on quirements of P.A. 74, Michigan P.A. on conformance with regulations and uctions of the United States Departs a Court of Law and/or that the corner the the rules of the Michigan Board of re-established, monumented, re-markets.	of 1970, the corner points mentioned rules therefore as required in the ment of the Interior, Bureau of Lar points mentioned in lines 3, 4 and Land Surveyors or by a Decree of conumented, recovered, found a	ed he he of the he h		
NC	NOTE: Not more than 4 corners, all in the same town and range, may be recorded					

on this certificate.

Description of original monument and accessories and/or subsequent restoration:

1845 GLO notes William Burt

12" Cedar

N42W 36 lks

16" Birch S60W 22 lks

1975 Jerry Wilcox found 3/4" square headed bolt, recorded in Liber A, page 185

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1997

Found 3/4" square headed bolt (Old witnesses)

5" Maple

S30E 20.15 feet

5" Cedar

S05W 31.96 feet

ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER PA. 345 OF 1990 AT A MEETING HELD ON 12-12-97

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1997 Found 3/4" square headed steel rod 12" in length removed. Set 1/2" rerod with remonumentation cap.

14" Spruce S80E

25.19

20" Spruce S75W 10" Maple

28.87

6" Cedar

S30E

20.031

31.98

S35W

HILL Land Burveyor No.

DECEMBER 22, 1997

Surveyor's Michigan License No.