

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 NR. 1 W.

Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sec.'s 16-17

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 6" Hard Maple S 52° E 52 1/2 links

Marked "1/4 S NBT"

4" Hard Maple N 52° W 16 1/2 links

Marked "1/4 S NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-established 1/4 corner midway and on line between two Section Corners. Numerous small cedar stumps in area. All badly burned. No evidence of cedar B.T.

Found several old blazes along 1/4 line west of this 1/4 corner.

SURVEYORS SEAL

SIGNED

REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 5/2/57