Cons. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line bet. two Sec. Cors. Found no evidence of original corner.

Distance south to stream is close to record. Stream is now a flooded beaver dam.

Corner lies in thick cedar swamp 70° north of wet tamarack and cedar swamp and is 100° east of an old log road.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

SIGNED Billy D. Buckler DATE 8-4-70

REGISTERED LAND SURVEYOR