JAN 21 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Mackinac County Remonumentation Corner

For	corners	in

Mackinac County	Located in:			Corner Code #
1. Public Land Survey		T42N T T	R01W R R R	C-9
	S S	T T	R R	
3. Miscellaneous Property in Sec.	S S	T T	R R	

DIANE FRANKOVICH MACHINAC COUNTY DEGICTE OF DEEDS


DEC 3 1 1998 為城 2.4 2006 2012 212 212 214 510

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat 5. Private Claims

I, Neil E. Hill, in a field survey on 12-21-98, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



6 7

8

9 10

39 lks

25 lks

A. Description of original monument and accessories and/or subsequent restoration:

			o ramaiaan	., 00 ,,	20110
1950'	's MSHD Plans ¾" ro	od 24.7' S	outh of CL M-13	34	
1993	R Bischer Fd ¾" Rod Liber D, Page 247	0	CL M-134 R/W Marker 12" Spruce 14" Spruce	Due North Due N S 06 W N 11 W	24.70' 99.70' 63.05' 83.75'

ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER P.A. 345 OF 1990 AT A MEETING HELD ON

36

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1998 Fd 3/4" rod and 3 witnesses Accepted corner location

1845 GLO Notes J Mullett

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

10" Tamarack S 68 E

6" Tamarack N 68 W

Corner is 3/4" rod

Corner is approx 25' South of CL of M-134

R/W Marker 12" Spruce 12" Spruce 12" Cedar	Due North S 06 W S 25 E S 50 W	99.70' 63.08' 53.34' 84.73'
12" Cedar	S 50 W	84.73
	S 50 W	84.73



Bearings are compass bearings, corrected for declination, all distances are to a double-headed nail in the side of the witness object unless otherwise noted.

للا Signed by

Date

Surveyor's Michigan License No. 27447