LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			· · · · · · · · · · · · · · · · · · ·
MACKINAC ICOUNTY!	Located In:	Corner Code ##	A.
Public Land Surv	T _42N_ R 4N T R T R T R		
Property Controll in Section Miscellaneous Property in Sec.		16 4000 T	Register of Deeds Stamp & File Number
	, Recorded Plat		A B C D E F G H I J K L M
5 Private Claims _			
in tines 1 and 2 above current manual of surv	16 Sep. 16 Sep	artment of the Interior, Bureau of the points mentioned in lines 3. 4	ot Land 7 4 and 5 8 19 20 21 22 23 24
above were in conformance with the rules of the Michigan Board of Land Surveyors of the above Courf of Law; established, re-established, monumented, re-monumented, recovered, found expressed below:			und as 10 30 29 26 27 26 25
NOTE: Not more to on this cert	han 4 corners, all in the same town lificate.	and range, may be recorded	11 12 13 13

- A. Description of original monument and accessories and/or subsequent restoration:
- (F6) CORNER PREVIOUSLY ESTABLISHED AND RECORDED UNDER ACT 74, P.A. 1970 BY BILLY D. BUCKLER IN 1980 AS 1" PIPE WITH 4" ALUMINUM CAP PLACED AT INTERSECTION OF LINES CONNECTING OPPOSITE 1/4 CORNERS. BUCKLER'S BT'S ARE: 10" S. MAPLE S29W B.O', 10" W. PINE M38E B.2', 6"
- (16) CORNER ESTABLISHED 5-2-1962 BY BILLY D. BUCKLER MIDWAY AND ON LINE BETWEEN DS AND ES. BUCKLER PLACED 1" PIPE WITH 4" ALUMINUM MI
- DEPT OF CONSERVATION TABLET. OBT'S: 4" S. MAPLE N72M 51 LINKS, 4" S. MAPLE N16E 31 LINKS. FOUND NO OTHER RECORD.
- (12) CORNER NOT ESTABLISHED IN ORIGINAL SURVEY. FOUND NO SUBSEQUENT RECORD.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (F6) FOUND AND ACCEPTED 1" PIPE CAPPED WITH 4" BIA. ALUMINUM MI DEPT. OF CONSERVATION TABLET, APPROPRIATELY STAMPED, IN ACCORD WITH N. PINE AND CEDAR BY'S ABOVE. MAPLE BY IS NOW A STUMP. ALSO FOUND SQUARED AND SCRIBED WOOD POST ADJACENT TO CORNER.
- (16) RECOVERED 1" PIPE PLACED BY BUCKLER WITH ALUMINUM TABLET MISSING. BUCKLER'S RECORD TIES CHECK AS SHOWN ABOVE (MAPLES ARE NOW
- 10"). DETERMINED PIPE TO BE 0.22'S AND 2.14'E OF BUCKLER'S INTENDED POSITION BUT ACCEPTED THE MUNUMENT AS A CAREFUL AND FAITHFUL DETERMINATION OF THE POSITION OF CORNER.
- (12) FOUND NO MOMUMENTATION AT THIS POSITION. ESTABLISHED CORNER EQUIDISTANT AND ON A STRAIGHT LINE BETWEEN MONUMENTED F6 AN F7. AT THE POSITION FOR THE CORNER, I PLACED A L"x30" PAINTED IRON PIPE CAPPED WITH A CAST ALUMINUM MICHIGAN DEPARTMENT OF NATURAL RESOURCES TABLET STAMPED TO IDENTIFY THE CORNER.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (12) SET I" PIPE WITH MOME TABLET. STON (16) FOUND 1" IRON PIPE. 10" R. MAPLE (FA) FOUND 1" PIPE WITH 4" ALUMINUM 13.78' N FACE THIN 24" BIRCH; \$628 N72H 33.7'; 10" R. MAPLE N16E 20.5'; B" TABLET. NSON 20.8' NE FACE 12" MAPLE; 23.60' SE FACE 18" HEMLOCK; NO4N 7.28" # HEMLOCK S64E 23.8'; 12" N. BIRCH S43N EAST 43.0' S. FACE 18" HEMLOCK; N38E FACE 8" MAPLE; \$44E 9.62" SN FACE 12" 18.6 . PLACED SQUARED POST ADJACENT TO 8.7' W. FACE 14" W. PIME (GRT); NETH MAPLE: NORTH 1' B" CEDAR POST SQUARED AND CORNER. DISTANCES ARE TO BY BLAZES. 15.9' W. FACE 8" CEBAR (OBT). DISTANCES SCRIBED. SBSN 39.2' FND PAINTED 2x2 NOOD BLAZED DBT'S AT BH, NBT'S AT BASE AND BH. ARE TO MAILS SET IN BRASS MONR REF. TAGS POST. DISTANCES TO BT'S ARE TO MAILS SET PLACED IN THE FACES NOTED. MRT'S WERE IN BRASS MONR REF. TAGS PLACED IN THE BLAZED AND SCRIBED AT BASE AND BH. OBT'S FACES NOTED. BLAZED AND SCRIBED ALL BT'S WERE FOUND SCRIBED AT BASE AND WERE AT BASE AND BH BLAZED AND SCRIBED AT BH. STEPHAN J. SZYSZKOSKI LAND 11-25-91

SURVEYOR Surveyor's Michigan License No ... 33986

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 20. 1971

O