

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T42... NR. 10 West

... Mackinac ... COUNTY

DESCRIPTION OF CORNER 1/4 corner for sections 5 and 8.

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 1-21-58

10" cedar N 71°, W 51 links. Marked "4S1BT"

12" white pine N 86°, E 95½ links. Marked "4S1BT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. Replaced corner from two tamarack bearing tree, bearing N 39°W 24 links west. Scribe marks "BT" notch in good condition. Also bearing N 68°, E 16 links. Tree down and rotted. Found by forestry division survey crew. 1/4 corner lies 1 chain north of small pond.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 6-18-59
REGISTERED LAND SURVEYOR