MAR 1 3 1998

1997 MACKINAC COUNTY REMONUMENTATION CORNER

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Mackinac County Located In:	Corner Code #	RECENTS 2 PRED
1. Public Land Survey T 42N R 1W T 43N R 1W T R T R	F-1 F-13)	DEC 5 1 1447 200 200 200 200 200 200 200 200 200 2
2. Property Controlling in Section S T R 3. Miscellaneous S T R		Register of Deeds Stamp & File Number
Property in Section S T R		negister of beeds stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims		A B C D E E G H J K L M
I, <u>David Guthrie</u> , in a field survey on <u>September</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1 in lines 1 and 2 above were in conformance with regulations and rules the manual of survey instructions of the United States Department of Management or by a decree of a Court of Law and/or that the corner is 5 above were in conformance with the rules of the Michigan Board of Decree of a Court of Law; established, re-established, monumented, re-	1970, the corner points mention herefore as required in the cure of the Interlor, Bureau of Le points mentioned in lines 3, 4 of Professional Surveyors or the professional Surveyors or professional Surveyors	oned 6 18 17 16 15 14 13 rrent 20 21 22 23 24 by a
as expressed below: NOTE: Not more than 4 corners, all in the same town and rang on this certificate.	ge, may be recorded	11
A. Description of original monument and accessories and/or subsequent restoration: 1840: GLO Survey by Wm. Burt - Set post and referenced: Sugar 6/N67°E/11 Sugar 6/N41°W/33 ACCEPTED BY THE MACKETAG COUNT SURVEY PEER GROUP AS THE OFFICIAL CURNEN UNDER PA. 345 OF 1990 AT A MEETING HELDON 12-19-97 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1997: Remonumentation Survey by R. S. Scott Associates, Inc.		
Found 3/4" Iron Pipe - Reference S46°W - 4" Maple (Exist.) S24°E - Utility Feriest.) N37°E - Utility Feriest.) N05°W - 10" Maple This corner position is compatible corner position is accepted as a lof the original corner.	erenced: - 30.10' Pole - 41.87' Pole - 43.82' e - 21.17' le with county a	and local surveys. This
C. Description of monument for corner and accessories est 1997: Placed 3" Mackinac County the 1/2" iron rod. Referenced: S46°W - 4" Maple S24°E - Utility F N37°E - Utility F N05°W - 10" Maple	cap stamped to - 30.10' Pole - 41.87' Pole - 43.82'	
Signed by Poll B. Circu	Date	-12-19-97

22435

Surveyor's Michigan License No.___

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983