## 1995 Mackinac County Remonumentation Corner

## LAND CORNER RECORDATION CERTIFICATE RECEIVED & FILED Filing Requirement of Act 74, Mich. P.A. 1970 DIANE FRANKOVICH For corners in MACKINAC COUNTY REGISTES OF DEEDS Located In: Corner Code # <u>Mackinac</u> NOV - 7 1995 AM ^ ^ ^ PM1. Public Land Survey T 43N\_ R \_\_1W 7[8]9[10]11[12[1]2[3]4[5]G T \_\_\_\_ R\_\_ T \_\_\_\_ R \_\_ 2. Property Controlling \_T \_\_\_ R\_ in Section S \_\_\_\_ R \_ 3. Miscellaneous S \_\_T \_\_\_\_R\_ Register of Deeds Stamp & File Number \_T \_\_\_\_R\_ Property in Section \_\_\_\_, Recorded Plat\_\_ 5. Private Claims \_\_ i,David B. Guthriein a field survey on in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 1845: Established by J.W. Mullett, G.L.O. Survey - Set post and referenced Birch 24 - S81E - 14 / Hem. 12 - N81W - 34 1979: Survey by Richards and Assoc. - Found 1/2" Iron Rod 1989: Survey by George J. Avendt - Found 1/2" Iron Rod. The Iron Rod as found by Richards and Assoc. lies 18.3 Ft. West and 3.67 Ft. North of this corner. 1994: Survey by Ronald Bischer - Found 1/2" Iron Rod as found by George B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1995: Found 1/2" Iron Rod. Another 1/2" Iron Rod lies 18.3 Feet West and 3.97 Feet North of this corner. SURVEY & ACCEPTED BY THE MACKINAC COUNTY REMONE ATION SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER P.A. 345 OF 1990 AT A MEETING HELDON 9 - R DEC 0 : 1995 HELDON COM SSION C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 1995: Placed a 3" Aluminum Cap stamped to identify the corner on a 1/2"x24" Iron Rod. This corner was set 6" below the road surface. Referenced - (Exist.) S86°W - 4" Apple - 75.76 Feet (Exist.) S35°E - Wood Post - 64.45 Feet (Exist.) N25°W - Utility Pole - 58.27 Feet (Exist.) N43°E - 6" Aspen - 76.55 Feet

DAVID B GUTHRIE ND SURVEY NO 22435

> EYORS, JAN. 28, 1971 EVISED MAY 14, 1975 REVISED JAN., 1983

22435

Signed by

Surveyor's Michigan License No.\_