SURVEY & REMONUMENTATION

MAR 1 3 1998 1997 Mackinac County Remonumentation Corner LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970.

For corners in SECTION Mackinac County) Located In: Corner Code #	70
(County)	RECEIVED & SHEED
1. Public Land Survey	DIANE PROTECULOR HERE CONTROL OF COME.
T R	DEC 3 1 /997
T R	AM PA
in Section S T R	图89304444463669
3. Miscellaneous S T R	Dogistor of Doods Champ C File Name
Property in Section S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	A B C D F F G H ; J K L t
5. Private Claims	2 6 5 4 3 2
	3
	4 7 8 9 10 11 12
I, <u>David B. Guthrie</u> , in a field survey onJuly <u>18</u> , 19 <u>97</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned	5
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land	6 18 17 18 15 14 13
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and	8 19 20 21 22 23 24
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found	9
as expressed below:	10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	11 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration;	13
1845: G.L.O. Survey by J.H. Mullett - Set Post and Referenced Sugar 20 / N70W / 21 Sugar 18 / S76E / 13 1969: Survey by Billy D. Buckler - Placed a 5/8" Iron Rod at road. Referenced - N27°W - Stop Sign - 46.7' N69°E - Stop Sign - 55.8' S20°E - Stop Sign - 58.8' S69°W - Stop Sign - 62.9' Recorded in Book 2, Page 635, Land Cor. B. Description of corner evidence found and/or method applled in restoring or reestablish 1997: Remonumentation survey by R.S. Scott Associates, Inc. Found Railroad spike at road intersection. Referenced - (Exist.) S26°W - Utility Pole - 126.85' (Exist.) S18°E - Utility Pole - 139.65' (Exist.) N23°W - Stop Sign - 49.20' N58°E - 8" Red Pine - 49.15' This corner position is compatible with County and local position is accepted as a careful and faithful perpetual of the original corner.	Records. (Cont'd on other side) ing corner: ACCEPTED BY THE MADKINAG COUNTY SURVEY FEER CACUP AS THE OFFICIAL CORNER UNDER PA. 345 OF 1990 AT A MEETING HELD ON 11-21-47 1 surveys. This corner tion of the position
C. Description of monument for corner and accessories established to perpetuate locating 1997: Placed 3" Mackinac County Cap stamped to identify the cin Monument Box. Referenced - \$26°W - Utility Pole - 126.85' \$18°E - Utility Pole - 139.65' \$N23°W - Stop Sign - 49.20' \$N58°E - 8" Red Pine - 49.15'	•
Signed by Vol B turn Date 12	2-19-97
DateDate	Y MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
	REVISED JAN., 1983

SURVEY & REMONUMENTATION

MAR 1 3 1998

SECTION

```
(Cont'd from other side)

A. 1996: Survey by Stephan J. Szyszkoski - Recovered 5/8" Iron Rod placed by Billy D. Buckler in 1969.

Referenced - S26°W - Utility Pole - 126.8'

S15°E - Utility Pole - 139.7'

N21°E - Utility Pole - 192.1'

N25°W - Stop Sign - 49.15'

L.C.R.C. Recorded in Book E, Page 129.
```

Land the state of the state of