Cons. 4047 REV. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 43 & 44 N.R. 7 W

		<u> Mackinac</u>	COUNTY
DESCRIPTION OF CORNERS	ection Corner for Sections	31/32 T44N R7W 6/5 T43N R7W	
CORNER HORWENT	" Iron Pipe with 4" Aluminu	m Cap	···
DATE MONUMENT PLACED AND W	THESSED _ 7/28/66 Frank J. B	ray	
WITHESSES TO CORNER환	Tamarack (S32 NBT) N 660	E. 16 Links	
8	" Cedar (S6 NBT) S 53° W, 3	7⅓ Links	
CIRCLE CORNER REGISTERED -	ND .		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed at wood post and 12 Iron Pipe set by unknown party. Tamarack stump (Tam. 10 S 17 E 32 Links) has axe marks and overgrowth of face no other evidence found.

SURVEYOR'S SEAL

SIGNED Prank J. Rray DATE 7/18/67