Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as recorded by D. A. Brotherton, R.L.S., 1917.

Found, 1" Iron Pipe buried 6.0' East of road intersection. Corner lies 33.0' East of N.-S. fenceline and equidistant between fence lines to west, which are 66.0' apart.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

Signed Billy D. Buckler, R.L.S. DATE 9/25/68

REGISTERED LAND SURVEYOR