MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 42-43 NR 10 W

			-	Macki	nac	COUNT
DESCRIPTION	OF	CORNER	Section_corner	çommon to S	iec.!s_3_/	<u>1-23-34</u>
DESCRIPTION	OF	CORNER	MONUMENT1	pipe_with_	4" brass	cap
WITTNESSES	то	CORNER	10" W. Pine	5 16° "S 3 NBT")_E	22 links
			_12" Soft_Maple		W	43 <u>links</u>
			10" Cedar	N 88°	E	48½ links
					. 	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced section corner from four B.T.s.

Found white pine stump bearing S 87° W 32 links. Blaze, notch and overgrowth in poor condition. White pine bearing N 44° E 22 links down and in poor condition. Jack pine bearing S 62° W 67 links. B.T. and notch plain, good condition. Jack pine bearing S 63° E 70 links, trace of notch remains.

Distance checks 5 links north to stream.

Corner found while searching for corners in area with Jim Halbach, District Forester.

Found several lines in area run by Jackson, Reg. Surveyor, St. Ignace.

SURVEYORS SEAL

SIGNED Silly D. Suchles DATE 7/17/57