

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42-43 NR 10-11 W.

----- Mackinac ----- COUNTY

DESCRIPTION OF CORNER Section corner common to Sec.'s 1-6-31-36, also township corner

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap -----

WITNESSES TO CORNER 6" Aspen ----- S 50° W ----- 17 links -----
"S 1 NBT"

6" Aspen ----- N 44° E ----- 28 links -----
"S 31 NBT"

7" W. Birch ----- N 24° W ----- 53 links -----
"S 36 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced corner. Found $1\frac{1}{2}$ " iron pipe set by unknown surveyor. Pipe sets in fence corner.

Found roots of tamarack bearing N 14° W 6 links.

Fence line running south and west. Found by Forestry Division Survey Crew.

Corner placed and witnessed January 14, 1958.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 1/21/58