## LAND CORNER RECORDATION CERTIFICATE

Ear companie	Filing Requiremen	nt of Act 74, Mich. P.A. 19	970 as Amended		
For corners in			,		
Mackinac	_ Located In:	Corner Code #			
(County)					
1. Public Land Survey	T <u>43N</u> R <u>12N</u>	C3			
	T R			•	
	TR				
2 Proporty Controlling	S TR				
2. Property Controlling in Section	S R				
3. Miscellaneous	S R		D1-4		
Property in Sec.	5 T R		Numbe	er of Deeds Stamp r	& File
	' <u></u> ' <u></u>		3 D C D		-
4. Lot No, Reco	orded Plat		1 A B C D	EFGHI.	J K L M
5. Private Claims			2 - 5 - 5 -	<del>┦┈</del> ┆╼┼╾┆╼┼╾	<b>?</b> ─┤─
	Dec 15	2003	3	<del>                                     </del>	<del>   </del>
, Stephan J. Szyszkoski	, in a field survey on	20 de hende	4 7 6	<del>  </del> 1 0	12-
that under requirements of P.A.	74, Michigan P.A. of 1970, the co	orner points mentioned in lines 1	y state 5	<del>                                     </del>	<del>   </del>
above were in conformance wit	h regulations and rules therefore	as required in the current mar	nual of 6 19 17	151	13-
survey instructions of the United	States Department of the Interior or that the corner points mention	or, Bureau of Land Management of	or by a 7	<del></del>	<del>                                     </del>
conformance with the rules of t	he Michigan Board of Land Surve	yors or by a Decree of a Court o	f Law: 8 -19 -20	<del>    2</del> 1-   22   2	3-24-
	numented, recovered, found as ex		9	<del> - - - - -</del>	
NOTE: Not more than 2 or	!! in the case Assum		10-30-29-	28 27 2	6-25-
NOTE: Not more than 2 co	orners, all in the same town	and range, may be recorde	11		
on and certificate.			12-31-32-	33 34 3	536
A. Description of original m	onument and accessories and	/or subsequent restoration:	13		
(C3) Corner common to Section	- 5 4 7 8 4 4077 0 0 0 1 1 1 1 1				
B. Description of corner ev	ridence found and/or method	applied in restoring or reest	ablishing corner:		
(C3) Found and accepted the 1	973 monument, in good condit	ion and at record bearing a	nd distance from the do	uble Maple, now 14	* DBH.
The Red Pine NBTs were not re					
•					
		:			
	· ·				
	,				
C Description of monument	for corner and accessories e	stablished to perpetuate loca	ating the position of the	Corner:	
(C3) Found 1/2" rebar. Blaze	d, scribed,	stabilished to perpetuate tool			
and set measuring nails in:		•		TE OF MICH,	Ł
14" twin Maple S77W 67.3'	"S7 NBT"		<b>13</b> /	STEPHAN J.	
14" Spruce N82E 13.35'	"S5 NBT"		# 4/	SZYSZKOSKI	* 8
12" Spruce S39E 20.25' 6" R.Pine N18W 36.8'	"S8 N8T" "S6 N8T"		*	LAND	不 N 本 要
o kirine miom solo Bearings are magnetic. Dista			13	SURVEYOR /	į
nail with tag.	11003 410 40		<b>1</b> 2	No. 33986	<i>}</i>
				00300	•
			**	AND SY	
D					
4.1				lalas	
Signed by	1 July Proce		_ Date	11117	
Surveyor's Michigan License	No. 33986	<del></del>			
	For the Michigan Departme	ent of Natural Resources, Of	fice of Land and Faciliti	es	
	. a. a.a mangan sapattin		ROVED BY MICHIGAN STATE BOAR	D OF PROFESSIONAL SURV	
					Revised May 14, 1975 Revised Jan., 1983
					Rervised Oct., 1995