CANS. 40.47 PEV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

	T. <u>44</u>	N. R	OM		
				Mackinac	COUNTY
DESCRIPTION OF CORNER	corner betwee	n Secs. 33	-34		
CORNER MONUMENT 1" pip	e with 4" alum	inum cap			
DATE MONUMENT PLACED AND 1	NITHESSED 4-30) - 69			
WITHESSES TO CORNER	9" Hard Mapl	Le (LS NBT)	S44 W 8.81		
N	10" Hard Mapl				
+	AND				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line bet. two Sec. corners. Found no evidence of original Cor. There is an irregular pine plantation edge about 60° west of corner.

Corner lies in pole-size hardwood timber.

SURVEYOR'S SEAL

Signed Billy B. Buckber DATE 6-19-69

REGISTERED LAND SURVEYOR