MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T44 NR 8 West

	MackinacCOUNT
DESCRIPTION OF CORNER	Section corner 24-25 on east boundary of township
DESCRIPTION OF CORNER	MONUMENT 1" pipe with 4" bress cap
WITNESSES TO CORNER .	6-9-58
	9" cedar S 60°, W 29 links. Marked "S25.BT"
	7" cedar N 70°, W 30 links. Marked "\$24%BT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. Replaced corner as set by Marcus Schaaf, Regional Surveyor. Found 2" iron pipe in place with two tamarack bearing trees, bearing N 34°, W 09 links, poor condition, tamarack stump bottom bearing, S 45°, W 06 links. Corner lies in swamp. Shown to us by J. Halbach, District Forester.

SURVEYORS SEAL

Silly D. Suckles

REGISTERED LAND SURVEYOR

DATE _6-18-59