## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_44. NR\_10 W\_\_

				Mackinac _	COUNT
DESCRIPTION	OF	CORNER	Section Corne	er_common_to_Secti	ions 2, 3, 10, 11
DESCRIPTION	OF	CORNER	MONUMENT	1" pipe with 4".	brass_cap
WIT TNESSES	то	CORNER	16" Cedar	S 85° E	6 links
			14"_Cedar_	s14° E	_34_links
				. <b></b>	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from one Tamarack B.T. in poor condition (fragment).

This (fragment) "B.T." now removed to the Mackinac State Forest office, Newberry.

Corner on South bank of stream 20. C - S. W.

Corner placed and witnessed March 14, 1956.

SURVEYORS SEAL

SIGNED\_Silly & Suchles DATE 3/19/56
REGISTERED LAND SURVEYOR