SURVEY & REMONUMENTATION

JAN 21 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Mackinac County Remonumentation Corner

F	0	r (CO	rn	e	rs	ir	١

roi comers in	í			IVED &	earer	
Mackinac	Located In:	Corner Code #	DIAN	COMMANDERSE SEERAN KO SEEN GES		J
1, Public Land Survey	Same T <u>44N</u> R <u>11W</u> Corner T <u>45N</u> R <u>11W</u> T R	D-13 (Luce)	ΔM	DEC 3 ₁ 199	8 PM	3
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R ACCEPTED BY TI	HE MACKINAC COUNTY		Deeds Stamp		mber
4. Lot No, 5. Private Claims,	Recorded Plat OFFICIAL CORNE 345 OF 1990 AT HELD ON 1/-2	R UNDER PA. A MEETING	1 A B C D	E F G H T T T T T T T T T T T T T T T T T T	J K	L)
of P.A. 74, Michigan P.A. of conformance with regulations instructions of the United State decree of a Court of Law and conformance with the rules of	urvey on November 23, 1993, do hereby state 1970, the corner points mentioned in lines 1 as and rules therefore as required in the currentes Department of the Interior, Bureau of Land dor that the corner points mentioned in lines of the Michigan Board of Land Surveyors or by hed, monumented, recovered, found as express	and 2 above were in it manual of survey d Management or by a 3, 4 and 5 above were in a Decree of a Court of	3 4 7 8 - 5 6 18 17 - 7 8 19 20 - 9	9 - 10	- 14 - 23	12 —
NOTE: Not more than 2 on this certificate	corners, all in the same town and range, e.	, may be recorded	10 30 29 -	28 — 27 — 33 — 34 —	- 26	-
	monument and accessories and/or subs mon to Section 32, Township 45 North R		on 5, Township 44	North Range 1	1 West.	

1841: Corner established by John Burt for William A. Burt -

Champion Internation Notes:

04/22/1976:

Calls for post

10/19/1978:

Calls for scribed post

Undated:

Calls for post set 14 1/2 links North of corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D-1) 1/4 Corner Common to Section 32, Township 45 North Range 11 West and Section 5, Township 44 North Range 11 West.

This corner is being perpetuated as part of the Mackinac County Remonumentation Program.

Corner reestablished as part of the Luce County Remonumentation program (1993.). Found a rotted off wood post with a 4" square wood post on North side. Found a wood corner fence post - the intersection of the the East right-of-way fence for the road to the North and a fence to the East. (Note: Road curves in area of corner - corner not In road). Approximately 500 feet North of the corner the right-of-way fences are 50 feet apart. Did not hold rotted off wood post for corner position. Reestablished corner position 25.0 feet West of the corner fence post on the extension of the fence line to the East. Wood post bears N24°W 9.8 feet from reestablished corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (D-1) 1/4 Corner Common to Section 32, Township 45 North Range 11 West and Section 5, Township 44 North Range 11 West. Corner is a 1/2" x 24" iron with a 3 1/4" diameter stamped aluminum cap, 6" below surface. Falls on Northeasterly edge of two track woods road (bears S65°E). Falls on extension of fence line to East (25 feet West of corner post). Falls on approximate extension of centerline Luce County Road 473 to North and West (road curves, gravel).

Witnesses:

NOTE:

Spruce 14" Cedar 10" (Twin) Yellow Birch 6" Cedar 9" (Triple) N48°E 36.00 feet S36°E 39.38 feet

S04°W 40.46 feet 4 S32°W 40.84 feet

All bearings are compass bearings corrected for declination. All distances are to a nail and tag in the

otherwise noted. Signed by _

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

KARR

LAND

SURVEYOR

REVISED JAN., 1983 REVISED OCT., 1995

c:\wpdocs\comerform\t45nrt1w.d-1

Surveyor's Michigan License No.