SURVEY & REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners	in		•		FEBZ7	1897	
MACO	(County)	Located In: Clinton Twp	Corner Code #		COMMIS	SION	
1. Public L	and Survey	T <u>2N</u> R <u>13E</u> T R T R T R	В3		ED BY THE MACOMB COL AS THE OFFICIAL CORNE		
•	/ Controlling	S TR	And the	PLIBLIC	ACT 345 OF 1990 MI	A MEETING HELD	
in Section		3 TR	Vegett a	ON	0-22-75	- Ci e	
3. Miscellaneous S T R					WILLIAM E. SODERBERG, P.S., CHAIRMAN		
					Register of Deeds S	tamp & File Number	
4. Lot No.	. Record	led Plat					
				1 A	B C D E F G	H I J K L M	
				2	-654- 	3-1-2-1-1	
I Crain D Am	not in a field armout	om May 26 1996 do be	white partific that under requirem	anto of	•		
P.A. 74, M	ichigan P.A. of 1970	, the corner points menti	reby certify that under requiremoned in lines 1 and 2 above v	vere in		1012	
	-	Termination of the state of the	ired in the current manual of Bureau of Land Management of		18 17 16	15 14 13	
decree of a	Court of Law and /or	that the corner points ment	ioned in lines 3, 4 and 5 above t	were in			
		•	Surveyors or by a Decree of a C nted, recovered, found as exp		_192021	22 23 24	
below:			•	9			
NOTE: Not more than 4 corners, all in the same town and range, may be recorded					_30_ 29 28	27 26 25	
on th	nis certificate.		•	11			
				12	_313233	34 -35 -36-	
A. Descrip	tion of original mon	ument and accessories a	and/or subsequent restoration	ı: ¹³			
1817	7 William Preston Set post			GLO			
none George Avendt #16034					corded Survey		
1972 1973	1972 Herbert Kobs #14097 1973 David South #20623				C L2279 P374 C L2464 P468		
1979	John Fenn #235		and ½" rerod in mon box	LCRC L31			
1982	Detroit Edison		½" pin in mon box	Notes	D004		
1989 1993	Martin Dunn #30 Bruce Antcliff #2		ind ½" iron in mon box ind ½" rod in mon box	LCRC L46			
		•	d applied in restoring or rees				
Road. The mor	The location was volument box, a Ma	witnessed prior to road	and iron in a monument boo construction. After comp mentation cap was set on a es.	letion of the	e road construction,	and resetting of	
C. Descrip	tion of monument f	or corner and accessorie	s established to perpetuate lo	ocating the po	osition of the corner:		
	ed existing found in ent MI 345 D3 3		rebar with a 2" diameter a	aluminum ca	ap stamped "Macomi	b County	
	0° 157.24'		enterline joint of Dalcoma		OF MICH	D	
•	0° 396.86' 1° 117.68'		enterline joint of Dalcoma		ALKE.	CA W	
	6° 144.30'	Set ½" rebar with "TRAV" cap at back of walk Set ½" rebar with "TRAV" cap at back of walk			CRAIG P.	N. A	
13	9° 75.93'	Set ½" rebar with	'TRAV" cap at back of wal	k	AMEY PROFESSIONA	, • * * }	
22	1° 74.82'	Set ½" rebar with	'TRAV" cap at back of wal	K	SURVEYOR	#0.63 #0.83	
			rally accepted by Professiona tion of the original corner.	al	AROFESSION	N. S.	
		00			12.9.96		
Signed by			Dat	te	12 1.10		
Surveyor's	Michigan Lice ns e	No. 34970					