SURVEY & REMONUMENTATION

APR 28 1995

or corners in

LAND CORNER RECORDATION CERTIFICATE

COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

94 DEC 14

EEDS TY MI MACOMB Corner Code # Located In: CLINTON (County) B-13 Public Land Survey 2N R 13E LIBER 6527 PAGE 853 R T R **Property Controlling** T R in Section Т Miscellaneous R Т Register of Deeds Stamp & File Number Property in Sec. R , Recorded Plat GHIJKLM Private Claims - 10 STEVEN E. DUNN , in a field survey on MARCH 20, 19 94 hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points nentioned in lines 1 and 2 above were in conformance with regulations and rules therefore a required in the current manual of survey instructions of the United States Department of e Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the orner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the ichigan Board of Land Surveyors or by a Decree of a Court of Law; established, -- 26 · --- 30 27 -established, monumented, re-monumented, recovered, found as expressed below: --- 31 --32 -- 36 - --- 35 --OTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN Description of original monument and accessories and/or subsequent restoration: PUBLIC ACT 345 OF 1890 AT A MEETING HELD 9 GLO POST - NO EVIDENCE OF ORIGINAL CORNER FOUND 13 dech GLO ORIGINAL SURVEY PERFORMED BY PRESTON 2-18-1818 WILLIAM E. SODERBERG, P.S., CHAIRMAN DESCRIPTION FOUND 1/2" ROD IN MONUMENT BOX <u>NAME AND NUMBER</u> WILLIAM J. COULTER, #14760 ..C.R.C DATE L. 5525 P. 750 AUGUST 5, 1992 L. 5665 P. 299 GERALD L. LANDWEHR, #10065 FOUND 1/2" REROD IN MONUMENT BOX **DECEMBER 1, 1992** PLATS L. 014 P. 027 ASSESSOR'S PLAT NO. 3 MARCH 20, 1930 L. 98 P. 40-41 BORIS PARK SUBDIVISION **DECEMBER 1992** L. 100 P. 1-7 HARRINGTON ESTATES SUBDIVISION **APRIL 1993** Description of corner evidence found and/or method applied in restoring or reestablishing corner: B-13 1/4 CORNER COMMON TO B-1 ERIN\LAKE TOWNSHIP FOUND 1/2" IRON ROD IN MONUMENT BOX IN CONCRETE PAVEMENT. VERIFIED LOCATION BY COMPARING FOUND WITNESS TIES OF L.C.R.C. LISTED BELOW AND COMPARING DISTANCE FROM B-13 TO A-13 OF PLATS BORIS PARK SUB AND HARRINGTON ESTATES SUB AND DISTANCE FROM B-13 TO C-13 OF ASSESSOR'S PLAT NO. 3. FOUND WITNESS TIES L. 5525 P. 750 NE 105.921 PK. NAIL IN 18" POPLAR S.06°W. 31.82' PK NAIL IN WEST FACE OF 36" WILLOW TREE L. 5665 P. 299 FIELD MEASUREMENTS AND RECORDED DISTANCES

B-13 TO A-13 2672.57' (M.) 2672.72' (R) HARRINGTON ESTATES SUBDIVISION AND BORIS PARK SUBDIVISION 2640.00' G.L.O. (R.) B-13 TO C-13 2697.74' (M.) 2697.50' (R) ASSESSOR'S PLAT NO. 3 2640.00' G.L.O. (R.)

. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-13 T.2N., R.13E.

WITNESSES

WITNESS	ES			STEVEN E.
N.5	8°E.	105.69'	FOUND PK NAIL IN WEST FACE OF 26" ELM.	* DUNN *
N.5	59°Е.	89.08'	TOP CENTER NUT ON HYDRANT.	PROFESSIONAL S
8.00	6°W.	31.821	FOUND PK NAIL AND TAG IN WEST FACE OF MULTIPLE STEM WILLOW.	No.
S.1-	4°E.	53.70'	FOUND PK NAIL AND TAG IN WEST FACE OF UTILITY POLE.	28408 SF ST
THE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BESSIONAL AND EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER				
gned by	Si	errn	E. Dum Date <u>Nov. 9, 19</u>	194
urveyor's Michigan License No. 28408				