SURVEY & REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

FEB 2 7 1997

MACOMB (County)		Located In: Clinton Twp				COMMISSION					
1. Public La	·	T_2N_R_13E_ TR TR	B3		PTED BY						
in Section	Controlling S on S	TR T R	Sep-th 2	PUBL	JP AS THE LIC ACT 3	45 OF 22-	-76		'		
3. Miscellaneous S T R				W	Dell	Lang E	-6	العيك	<u>م</u>		
Property	in Sec. S	TR			WILLIAM Re	E. SODE	RBERG, ' Deeds	P.S., Ch Stamp	& File	v Number	
				٠							
		Plat			а в с	DE	F G	н і	Ji	LM	
5. Private (Claims					ŢŢ	ŢŢ	ŢŢ	Ţ		
			•		3 6 6	_ 5	-4	- 3 - 	2_		
P.A. 74, Miconformance instructions decree of a Conformance Law; establis	chigan P.A. of 1970, the with regulations and ru of the United States Dep Court of Law and /or that with the rules of the Mic	e corner points mentione iles therefore as required artment of the Interior, Bu the corner points mention chigan Board of Land Surv	y certify that under requiremed in lines 1 and 2 above to in the current manual of ureau of Land Management and in lines 3, 4 and 5 above veyors or by a Decree of a Cd, recovered, found as exp	ents of were in survey or by a were in Court of	4 _ 7 _ 5 _ 6 _ 18 _ 7 _ 8 _ 19 _	17	-16 -21	-10	11	12 	
below:					9 -						
NOTE: Not more than 4 corners, all in the same town and range, may be recorded						29	_28	-27	—26—	_25_	
on th	is certificate.			1	11	-++	-		-		
			0	1	12 31	_32	_3'3	_34_	3 ¹ 5 ¹	-36-	
A. Descrip	tion of original monume	ent and accessories and	or subsequent restoration	n: :	13						
1817 none	William Preston George Avendt #166	Set po		GLO Unreco	orded Su	rvey					
1972	Herbert Kobs #1409		l ½" iron bar		L2279 P						
1973 1979	David South #20623 John Fenn #23505		l #4 rebar l ½" rerod in mon box		L2464 P L3184 P						
1979	Detroit Edison		" pin in mon box	Notes	L3 104 F	5//					
1989	Martin Dunn #3008		1 %" iron in mon box		L4687 P	331					
1993	Bruce Antcliff #258	26 Found	l ½" rod in mon box	LCRC I	L6161 P.	238					
B. Descrip	tion of corner evidence	found and/or method a	pplied in restoring or rees	tablishing	corner:						
Road. T	The location was witroument box, a Macom	essed prior to road co	iron in a monument bo postruction. After comp ntation cap was set on	oletion of	the road	constru	uction	, and i	resetti	ng of	
C. Descrip	tion of monument for c	orner and accessories e	stablished to perpetuate l	ocating the	e position	of the	corner	:			
	d existing found iron ent MI 345 D3 3497		bar with a 2" diameter	aluminum	cap sta	mped "l	Macor	nb Co	unty		
(terline joint of Dalcoma			ALL S	EMA	M			
			terline joint of Dalcoma		B	XE U	• • • • • • • •	HIG	Br.		
			RAV" cap at back of wal		190	?` . ••			· B		
13:			IAV" cap at back of wal IAV" cap at back of wal		# ×	•	RAIG P. AMEY	•	* * N		
22			RAV" cap at back of wal			PROF	ESSIO		<u> </u>		
	The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.							NAL SU	26.5		
	1. D	1	1		17.	9.91					
Signed by		77	Da	te	62.	1.16			****		
Surveyor's	Michigan License No	34970									