SURVEY & REMONUMENTATION

APR 2 8 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

C104998

			-0-	
٦r	COMPARE	in		

Macomb (County)	Located in: She1by Corner Code #	118FRU0413Fb4 F3
 Public Land Survey Property Controlling 	T 3 N R 12 E E-2 T R T R T R S T R	CAMMEL SABAUGH REGISTER OF DEEDS MACOME COUNTY MET
in Section 3. Miscellaneous Property in Sec.	S T R S T R S T R	Register of Deeds Stamp & File Number
	Recorded Plat	A B C D E F G H 1 J K L N
do hereby certify that under re in lines 1 and 2 above were in current manual of survey instr Management or by a decree of above were in conformance w	, in a field survey on July 5 , 1 equirements of P.A. 74, Michigan P.A. of 1970, the corner point in conformance with regulations and rules therefore as recructions of the United States Department of the Interior, Buf a Court of Law and/or that the corner points mentioned in limit the rules of the Michigan Board of Land Surveyors or by a re-established, monumented, re-monumented, recovered	ts mentioned quired in the preau of Land nes 3, 4 and 5 a Decree of a d, found as
NOTE: Not more than 4 of on this certificate	corners, all in the same town and range, may be rec	orded 11 32 33 34 35 36

- A. Description of original monument and accessories and/or subsequent restoration:
 - 1817-GLO Wampler, D.S.; Set Post; 14" White Oak S48*W 24 Links; 14" White Oak S68*E 19 Links
 - 1.) 1976-Avey, P.S. #15396; LCRC L.2666, Pg.852 Fnd 1/2" Pipe in a Monument Box
 - 2.) 1979-Kobs, P.S. #14097; LCRC L.3126, Pg.162 Fnd 1/2" Pipe in a Honument Box 3.) 1988-Avey, P.S. #30076; LCRC L.4353, Pg.434 Fnd 1/2" Pipe in a Honument Box

 - 4.) 1993-Avey, P.S. #30076; LCRC L.5947, Pg.064 Fnd 1/2" Pipe in a Monument Box
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 1994 Kennedy Surveying, Inc. Kennedy, P.S. #17623 Fnd 1/2" Iron Pipe in a Monument Box 4' West of the centerline of Mound Road, which has a bituminous surface, and a tree row extending to the East & West on the South side of a gas easement.

The witnesses from LCRC #1, 2, 3 & 4 were used to recover and verify the location of the found 1/2" Iron Pipe in a Monument Box.

FIELD MEASUREMENT BETWEEN

E-2 to E-1 2874.30 Feet E-2 to E-3 2640.53 Feet ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN 845 OF 1890 AT A MEETING HELD WILLIAM E. SODERBERG, P.S., CHAIRMAN

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-2 I replaced the found 1/2" Iron Pipe in a Monument Box with a 3/4" x 24" Iron Rod w/2" diameter aluminum cap stamped "Macomb County Monument HI Act 345 #17623" in a existing Monument Box. MANUAL OF MICHAEL

S84°E 44.25' Set PK & Remon. Washer South face 14" Poplar

S21'W 98.14' Set PK & Remon. Washer East face Power Pole

S78°W 29.97' Set PK & Remon. Washer North face 10" Elm

N29°W 124.91' Set PK & Remon. Washer NE face Power Pole

The selected location is accepted by me and is generally accepted by Professional Surveyors as the position of the original corner. position of the original corner.

vai Kan Ne Orden ROFESSIONAL AND SURVEYOR REVIEW Date . July 21, _1994

17623 Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975