## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 197 (ECORDE) IN MACOMO COUNTY For corners in RECORDS AT: 8:30 A M. Located In: Macomb Corner Code ## Shelby Twp. DEC 28 1993 T 3 N R 12 E 1. Public Land Survey T \_\_\_\_\_ R \_\_\_\_ T \_\_\_\_\_ R \_\_ T \_\_\_\_ R \_\_\_\_ Property Controlling \_\_ T \_\_\_\_ R \_\_\_\_ S \_\_\_\_ T \_\_\_ R \_\_\_\_ in Section Miscellaneous S \_\_\_\_ R \_\_\_\_ Register of Deeds Stamp & File Number Property in Sec. \_\_ , Recorded Plat \_\_ 4. Lot No. \_ 5. Private Claims ... 2 3 6 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 8 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a 9 Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 12 A. Description of original monument and accessories and/or subsequent restoration: 1817-GLO Wampler, D.S.; Set Post; 11" Ash S54°W 28 Lnks; 9" Ash N85°E 23 Lnks 1972-Avey, P.S. #15396; LCRC L.2268, Pg.54 - Fnd 5/8" Iron Rod in a monument box 1974-Kobs, P.S. #14097; LCRC L.2534, Pg.471 - Fnd 1/2" Iron Rod 1979-Fenn, P.S. #23505; LCRC L.3168, Pg.264 - Fnd 3/8" Iron Rod 1986-Avey, P.S. #30076; LCRC L.3945, Pg.714 - Fnd 1/2" Iron Rod #17635 in monument box 1990-Avey, P.S. #30076; LCRC L.4983, Pg.766 - Fnd 1/2" Iron Rod #17635 in monument box B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1993 Kennedy Surveying, Inc. - Kennedy, P.S. #17623 - Fnd 1/2" Iron Rod in a monument box located in the centerline of Jewell Road to the North, and 1.5' North of the centerline of 24 Mile Road. Both are bituminous surface roads. All witnesses from the fifth LCRC above were found and they were used to recover and verify the location of the found 1/2" Iron MACOMB Rod in a monument box. ACCEPTED BY THE COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 A MEETING 1990 AT 12-20-9 FRANK J. DeDECKER, PS, PE, CHAIRMAN C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: I-5 I replaced the found 1/2" Iron Rod in a monument box with 3/4" x 24" Iron Rod w/2" diameter aluminum cap stamped "Macomb County Monument MI Act 345 #17623" in a monument box. N40°E-46.31'-Set PK & Remon. tag in SW face Power Pole N74°W-127.51'-Set PK & Remon. tag in SW face 27" Elm  $\mathrm{S72}^{\circ}\mathrm{W}\text{-}94.41'\text{-Set PK & Remon. tag SE face Power Pole}$ S05°E-26.03'-Set PK & Remon. tag West face Power Pole The selected location is accepted by me and is generally accepted by Professional Surveyors as the best and HUSTON position of the original corner. KENNFDY LAND AND JAN. 28, 1971 Surveyor's Michigan License No. . ORM APPROVED BY MICHIGAN STATE BOAI

 $\frac{\lambda}{\delta n}$