## LAND CORNER RECORDATION CERTIFICATE

Εo	r corners in	Filing Requirement of Act 74, Mich. P.A. 1970 From MARKED COUNT						
Macomb		Located In:	Corner Code ##	RECORDS A ST	8:30 A	VI.		
	(County)	Shelby Twp.	Comer Code	nro o	10.1000			
1.	Public Land Survey	т <u>З N</u> в <u>12 E</u> т R т В	<u>K-4</u>		8 8 1993 Assengt	/		
		T R						
2.	Property Controlling	S R		MACOMS COUNTY	. MICHIGANU			
2	in Section Miscellaneous	S T R S T R		Danista, of	Danda Ctamb G	Pila Manakan		
٥.	Property in Sec.	S T R		Register of Deeds Stamp & File Number				
		5 4 4 5 4						
		Recorded Plat			CDEFG	HIJKLM		
J.	Titate Olding	,		2 - 6-		_		
				3 4 7	1111	<del>                                     </del>		
1	Huston K. Kenned	Y , in a field survey onDece	mber 14 19 _93		8 9 1			
do	hereby certify that under r	requirements of P.A. 74, Michigan P.A. of	1970, the corner points me	ntioned 6 1	17—16—	15-14-13-		
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land								
Management or by a decree of a Court of Law and/or that the corner points mentione above were in conformance with the rules of the Michigan Board of Land Surveyors				4 and 5 8 19	20-21-			
above were in conformance with the rules of the Michigan Board of Land Survicourt of Law; established, re-established, monumented, re-monumented			numented, recovered, for	und as	+++++			
expressed below:			1030	29 28	_2 <del>'</del> 7			
NC		corners, all in the same town and	range, may be recorde	ed 11				
	on this certificat	в.		13	32 33	34 35 36		
В.	1817-GLO Wampler, D.S.; Set Post; 8" White Oak N61 1/2°W 16 Lnks; 6" Haple N68 1/2°E 23 Lnks 1976-Avey, P.S. #15396; Survey L.2717, Pg.305 - Fnd 5/8" Iron Rod in a monument box 1976-Avey, P.S. #15396; LCRC L.2718, Pg.736 - Same wits as 1976 survey 1978-Avey, P.S. #15396; Survey L.3001, Pg.173 - Same wits as 1976 survey 1978-Kobs, P.S. #14097; Survey L.3021, Pg.189 - Fnd 5/8" Iron Rod in a monument box 1978-Kobs, P.S. #14097; LCRC L.3021, Pg.205 - Same wits as 1978 survey 1987-King, P.S. #30085; LCRC L.4151, Pg.126 - Fnd 1/2" Iron Rod 1990-Avey, P.S. #30076; LCRC L.4983, Pg.762 - Fnd 1/2" Iron Rod in monument box 1992-Avey, P.S. #30076; Survey L.5290, Pg.298-299 - Same wits as 1990 LCRC  Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1993 Kennedy Surveying, Inc Kennedy, P.S. #17623 - Fnd 1/2" Iron Rod in a monument box located in the centerline of Schoenhern Road, which bituminous surface. There are tree lines extending to the East and West.  One witness point from the 1990 LCRC was found and it was used to recover and verify the location of the found 1/2" Iron Rod							
	in a monument bo	in a monument box.		D BY THE	MACOME	COUNTY		
			SURVEY	PEER GROU UNDER MICH	IGAN PUB	LIC ACT 345		
			OF 1990		EETING	HELD ON		
				-20-93	·•			
				$\Delta \cap \Delta $	<u> </u>			
				Tyour	della ne i	DE CHAIRMAN		
^	ing and the second seco	ment for corner and accessories es	tablished to nemelicate	FRANK J. Del	DECKER, PS, P	E, CHAIRMAN		
G.								
	Monument MI Act N43°E-39.27'-Set PK N85°E-53.57'-Set PK	ound 1/2" Iron Rod in a monument bo 345 #17623" in a monument box. & Remon. tag NW face 29" Ash & Remon. tag North face Power Pole		Rod W/2 <sup>n</sup> diameter a	luminum cap sta	mped "Macomb Count		
	S47°E-101.40'-Set PK & Remon. tag NE face 13" Maple S89°W-52.83'-Set PK & Remon. tag North face Power Pole							
					September 14.	EUT WICHING		
	The selected location position of the	on is accepted by me and is general coriginal corner.				KENNEDY LAND		
Sid	aned by	<u></u>	Date	2-14-93	EG.	SURVEYOR 2- 17623 0-3		
-	rveyor's Michigan Lice	nse No. 17623		FORM APPROVED BY MIC	HIGAN STATE BOOMS AND	AND SURVEYORS LANGE 19		
Ju	yor o miorngan Elee		:	JOHN MINUTED OF MID	Tita	CORREGOES REVISED JAN., 191		