LAND CORNER RECORDATION CERTIFICATE MAR 17 2000 Filing Requirement of Act 74, Mich. P.A. 1970 For comers in SECTION 1091827 LIBER 9268 PAGE 15 12/27/1999 01:15:42 P.M. MACOMB COUNTY, MI CARMELLA SABAUGH, REG/DEEDS MACOMB Localed in: Comer Code # MACOMB TWP. 1. Public Land Survey F-3 T3N R13E R R R 2. Property Controlling S R in Section S Т R 3. Miscellaneous S R Property in Sec. Register of Deeds Stamp & File Number , Recorded Plat 4. Lot No. 5. Private Claims 2 I, GEORGE M. PLATZ I, GEORGE M. PLATZ , in a field survey on APRIL 19 ,1999 , do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey 3 5 instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the 6 rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, 7 monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded 9 on this certificate. 10 11 12 A. Description of original monument and accessories and/or subsequent restoration: 1817 Set Post Notes Preston Notes N/A #10868 1974 بهرا L.2544 P.224 Iron bar Buckerfield LCRC J. 1974 Iron bar #14097 L.2569 P.83 Survey н. Kobs 1975 ∀″ Iron bar LCRC H. Kobs #14097 L.2569 P.89 1977 #16034 L.2870 P.783 Iron bar Survey G. Avendt ע" Iron bar Survey 1985 н. Kobs #14097 L.3880 P.61 14" 1988 L-4543 P.70 Iron bar Survey H. Kobs #14097 3/4" 1994 Rod w/Remonumentation cap in box
1/2" Iron Rod in box LCRC R. Kohn #26459 L.6523 P.927 1997 LCRC #43056 L.7734 P.494 C. Hein Description of comer evidence found and/or method applied in restoring or reestablishing corner: Found 1/2" rod in monument box approximately 2' south of the centerline of the existing asphalt pavement of 25 Mile Road. 3 remaining witness ties from LCRC L.7734, P.494 along with field measurement to adjacent corners verified its position. Remaining witness ties 43.65' 67.24' (M) (M) S01W 43.61' N66E 91.66' 91.59' N75W (M) ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN Field measurements to adjacent corners: PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON 10/24/9 2684.86' E-3 to F-3 2684.85' (R) L.6523 P.927 LCRC 2684.85 (R) L.7734 P.494 LCRC WILLIAM E. SODERBERG, P.S., CHAIRMAN 2682.57' F-3 to G-3 (M) 2682.46' L.6523 P.927 LCRC (R) 2682.58' (R) L.7734 P.494 LCRC C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: I accepted the found 1/2" rod in monument box. Set 2" diamete Monument MI Act 345 #38121" and re-witnessed point as follows: Set 2" diameter aluminum cap stamped 'Macomb County Az. 134° Set PK with SDA tag No. 38121 on top of last guard rail post West of drain Az. 184° 43.72' Found PK with CPA tag in West face of utility pole Az. 288° 91.664 Found PK with M.C.R.C. tag in SW face of utility pole Az. 348° Set PK with SDA tag No. 38121 on top of last guard rail post West of drain The selected location is accepted by me and generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Date

| Complete | Complet Signed by

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SERVEYORS, JAN. 28, 1971
REVISED MAY 14,1976
REVISED JAN, 1983
REVISED JAN, 1983

No.

Surveyor's Michigan License No. 38121