LAND CORNER RECORDATION CERTIFICATE

SURVEY &

For corners in	Filing Requirement of Act 74, Mich. P.A.			REMONUMENTATION
Macomb (County)	_ Located in: Macomi	Twp. Corner Code	e #	APR 0 7 1998
 Public Land Survey Property Controlling in Section Miscellaneous Property in Sec. 	T3:N R-13-E H-1 SECTION T R TR			
4. Lot No Recorded Plat				
5. Private Claims				A B C D E F G H I J K L M 1
I, John N. Redash, in a field survey on October 16, 19.97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:				4 7 8 9 10 11 12 5 6 19 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 20 20 27 26 25
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.				10 30 29 20 27 26 25 11 12 31 32 33 34 35 36 13
A. Description of original monument and accessories and/or subsequent restoration:				
1979 P.K Nail in pave	Not set G.L.O. Notes W. Preston P.K. Nail in pavement L.C.R.C. H. Kobs P.K Nail in pavement Survey H. Kobs P.K. Nail in pavement Survey D. King			N/A L3186, P870 L3186, P879 L4866, P823
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:				
No corner found at above described position. A P.K. Nail was set in asphalt pavement from witnesses on L.C.R.C. (L3186, P870). Field observations were obtained between the following corners and found nail following 0-31 north of line H-13 - G-13. Further set nail 0.31 south and on line H-13 to G-13.				
G-1 to H-1 H-1 to I-1 2690.53 meas. 2689.86 meas. No G.L.O. No. G.L.O. 2690.35 Rec. Survey, L4866, P823 2689.92 Rec. Survey L3186, P879				eas. ec. Survey L4866, P823 ec. Survey L3186, P879
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:				
I replaced the set P.K. Na Act 345 #37281" in a ne	nil with a 3/4" X 24" iron www.monument box in asp	rod with a 2" alun halt pavement. Wi	ninum disk sta tness ties are	amped "Macomb County Monument MI as follows:
Due East 87.22' Macomb County Remon. Cap #37281 and iron in monument box (H-13) T-4-N., R-13E SET P.K. nail and Macomb County Remon. tag N.E. face 48" Oak S. 26° E., 38.91' Cross in west face of 6" steel post Cross in east face of 6" steel post SURVEYOR NO.				
The selected location is accepted by me and generally accepted by Professional Surveyors as the best available evidence 37281 of the position of the original corner Signed by Date December 16, 1977 Surveyor's Michigan License No. 37281				
Date December 16, 1997				
Surveyor's Michigan License No. 37281 FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 197				

REVISED JAN., 1983 REVISED OCT., 1995

GCESTED BY THE MACOMB COUNTY SURVEY PEER GTOUP AS THE OFFICIAL CORNER UNDER MICHIGAN FUBLIC ACT 345 OF 1990 AT A MEETING HELD ON WILLIAM E. SODERBERG, P.S., CHARMAN