SURVEY & **REMONUMENTATION**

Signed by

Surveyor's Michigan License N

34970

C015A335 | TBER:06543 PAGE:357 06:350 01/05/1995

MACONAR	Located Inc	Camas Ca	
or corners in			1
COMMISSION		LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970	
APR 2 8 1995AR	MELLA SABAUGH-MAC	OMB COUNTY, M	II REG/DEEDS

Located In: Corner Code # CHESTERFIELD TOWNSHIP 1. Public Land Survey 3N R 14E R 2. Property Controlling in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number _, Recorded Plat 4. Lot No. 5. Private Claims 3 , in a field survey on . , 19<u>94</u> CRAIG P. AMEY AUGUST 25 hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as 5 required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, 8 re-monumented, recovered, found as expressed below: 10 NOTE: Not more that 4 corners, all in the same town and range, may be recorded on this certificate. 11 A. Description of original monument and accessories and/or subsequent restoration: Pages 55-57 William Preston No witnesses found 1817 G.L.O. Found, 1/2" rerod Liber 3168 Page 267 John R Fenn, #23505 1979 LCRC Found, 1/2" rerod Found, 1/2" iron bar w/cap #5557 1979 LCRC Liber 3179 Page 738 William E Soderberg, #17635 Liber 3465 Page 178 Liber 0487 Page 333 1983 LCRC Herbert J. Kobs, #14097 Found, 1/2" iron rod 1989 LCRC Martin C. Dunn, #30081 Corner is common to M-3 T3N, R13E Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found: 1/2" rebar with damaged cap, 0.3' below the surface of twenty file mile road (gravel) This corner verified by: found and matched existing witnesses E MACOMB COUNTION TO THE TOTAL CORNER UNITED TO THE TOTAL CORNER UNITED TO THE TOTAL CORNER OF THE TOTAL C 1979 LCRC Liber 3168 Page 267 Found, 1/2 Rerod 25.79 South Found. Pk nail in fence post 65.25' Southwest Found, Pk nail in d.e. Pole 41.73 W/southwest Pk nail in 6" ash Found. 44.00 Northwest Pk nail in d.e. Pole Found. Liber 3179 Page 738 Found, 1/2" rerod 1979 LCRC 43.99 Northwest Found. Pk nail in southwest face of d.e. Pole 65.28 Southwest Found. Pk nail in southeast face of d.e. Pole 25.801 South Found, Pk nail in west face fence post 1989 LCRC Liber 4687 Page 333 Found, 1/2" rerod ¥ 43.99' Northwest Found. Pk nail in southwest face of d.e. Pole GROUP, 65.281 Pk nail in southeast face of d.e. Pole Southwest Found. 25.80 South Found. Pk nail in west face fence post 2664.681 North To the west quarter post of section 6 South 2665.21 To the west quarter post of section 7 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner SATE OF MICHIGAN Replaced 1/2" rerod with a 3/4" x 24" iron and a Macomb County Remonumentation cap stamped: "MACOMB COOK.

25.84' PK and MCR tag in the west side of a DE pole.

65.29' PK and MCR tag in the southeast side of a triple 8" ash

V 41.64' PK and MCR tag in the southwest face of a DE pole

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner

12.15.54

12.15.54 SW WSW 41.64' AMEY PROFESSIONAL NW A ROFESSIONA