LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1978 ORDED IN MACOMB COUNTY For corners in RECORDS AT: 8:30AM MACOMB Located In: Corner Code ##
Chesterfield Township (County) DEC 28 1993 T 3N R 14E Public Land Survey __ R _ B ___ R _ OLERK - REGISTER OF DEEDS MACONE COUNTY, MICHORA 2. Property Controlling ____ T ___ R _ in Section _ T .__ __ R _ S Miscellaneous Register of Deeds Stamp & File Number Property in Sec. 4. Lot No. ______, Recorded Plat __ 5. Private Claims _ She1by W. Money, in a field survey on November 18 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 12 Description of original monument and accessories and/or subsequent restoration: CLO POST. NO WITNESSES REMAIN STEVE DUNN #30081 L.2433 P.39 SAITH #16052 (1973) IRON FÖLDD (RÖN SOUTHWEST 30.25' SOUTHEASTERLY CORNER OF FRAME BARN SOUTHEAST 3.15' CORNER OF THE OLD FOUNDATION SOUTHEAST 67.73' NORTHWESTERLY CORNER OF GARAGE
 CCRC
 (1991)
 L.5024
 P.935
 Dedecker #8386

 FOLND
 1/2" IRON ROD
 AZ
 25.*
 37.97 PK
 W/SDA TAG IN CONCRETE PAVEMENT @ COKNER OF BUILDING #50002

 AZ
 170.
 8.63 PK
 PK W/SDA TAG IN THE EAST FACE OF TOT TREE
 12" TREES

 AZ
 276.
 17:15 PK
 W/SDA TAG IN THE NORTH FACE OF TOT TREE

 AZ
 328.
 69:42'
 PK W/SDA TAG IN SOUTHWEST CORNER OF CONCRETE PAD FOR DE TRANSFORMER
 Description of corner evidence found and/or method applied in restoring or reestablishing corner; FOUND 1/2" REBAR IN GOOD CONDITION c-8 ACCEPTED BY THE MACOMB THIS CORNER VERIFIED BY: FOUND MOST WITNESSES SURVEY PEER GROUP AS THE OFFICIAL CERTIFICATE OF SURVEY
CERTIFICATE OF SURVEY LIBER 2433 LIBER 3461 PAGE 37-3 **CORNER UNDER MICHIGAN PUBLIC ACT 345 PAGE 307** 1990 AT MEETING HELD 12-15 FRANK J. DeDECKER, PS. PE, CHAIRMAN Description of monument for corner and accessories established to perpetuate locating the position of the corner: REMOVE 1/2" REBAR AND REPLACED WITH A 3/4" BAR WITH MACOMB COUNTY REMONUMENTATION MARKER #39002 WITNESSES FROM LIBER 5024 PAGE 935: c-8 WITNESSES FROM LIBER 5024 Az 25. 57.97' FOUND PK W/SDA TAG IN CONCRETE PAVEMENT @ CORNER OF BUILDING #50002
FOUND PK W/SDA TAG IN THE EAST FACE OF TRIPLE 14" TREES
FOUND PK W/SDA TAG IN THE NORTH FACE OF 10" TREE
FOUND PK W/SDA TAG IN SOUTHWEST CORNER OF CONCRETE PAD FOR DE TRANSFORMER Az 25• Az 170• Az 276 • Az 325 • SILE OF MICHIGA SHELBY W. The selected location is accepted by me and is generally accepted by Professional Surveyor MONEY as the best available evidence of the position of the original corner. **PROFESSIONAL** SURVEYOR _ Date /2/14/93 Surveyor's Michigan License No. __