SURVEY & REMONUMENTATION

APR 2 8 1995

٦r Μż

Private Claims _

C152192

A 100 C	2 % 2	-	P 3
CON	nw	300	1 11

LAND CORNER RECORDATION CERTIFICATE

corners in	MVIIOSICIN Filing Requirement of Act 74, Mich. P.	
acomb (County)	Washington Located In: Twp. Corner Code ##	LIBER 6527 PAGE 769
Public Land Survey	T 4N R 12E E-5 T R T R T R	94 DEC 14 AM 10: 50 CARA REGIST DEEDS MACCON AND MITTY, MI
Property Controlling	S T R	MACONDIAN DEEDS
in Section	S T R	
Miscellaneous	S T R	Register of Deeds Stamp & File Number
Property in Sec.	S T R	— ABCDEFGHIJK

Huston K. Kennedy a field survey on September 10 hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned ines 1 and 2 above were in conformance with regulations and rules therefore as required in the rrent manual of survey instructions of the United States Department of the Interior, Bureau of Land nagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 ove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a urt of Law; established, re-established, monumented, re-monumented, recovered, found as ressed below:

TE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11

Description of original monument and accessories and/or subsequent restoration:

17-GLO Wampler, D.S.; Set Post; 16" White Oak N88'E 65 Links; 15" Black Oak N77'W 1.90 Links

1983-Kobs, P.S. #14097; LCRC L.3532, Pg.264 - Fnd 1/2" Pipe

1986-Kobs, P.S. #14097; Survey L.3900, Pg.803 - Fnd 1/2" Pipe

1993-Kobs, P.S. #14097; Survey L.5831, Pg.257 - Fnd 1/2" Pipe, used same wit as 1986 Survey

1993-Kobs, P.S. #14097; Survey L.5969, Pg.150 - Fnd 1/2" Pipe, used same wit as 1986 Survey

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

4 Kennedy Surveying, Inc. - Kennedy, P.S. #17623 - Fnd 1/2" Iron Pipe 8" deep 1.7 feet East of the centerline of Hound Road, which has a bituminous surface, and 16 feet South of the centerline of 30 Mile Road, which has a gravel surface and extends to the East. There is a tree-fence line extending to the West.

Witnesses from LCRC #1 and Survey #2 were used to recover and verify the location of the found 1/2" Iron Pipe.

FIELD MRASUREMENT BETWEEN

E-5 to F-5 2689.32 Feet E-5 to E-6 2631.49 Feet ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD

رمح

WILLIAM E. SODERBERG, P.S., CHAIRMAN

Description of monument for corner and accessories established to perpetuate locating the position of the corner.

I replaced the found 1/2" Iron Pipe with a 3/4" x 24" Iron Rod w/2" diameter aluminum cap stamped "Macomb County Honument MI Act 345 #17623" in a new Monument Box. TE OF MICHE

S45 W 64.30' Set PK & Remon. Washer SE face 14" Pine

S81°W 38.67' Set PK & Remon. Washer South face 13" Box Elder

N50°E 57.53' Set PK & Remon. Washer SE face Power Pole

S58'E 26.48' Set PK & Remon. Washer NE face 15" Box Elder

selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of ition of the original corner.

REVISED JAN., 1983

S. Maria September 20, 1994 Date ___ FDAM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 eyor's Michigan License No. 7623 REVISED MAY 14, 1975