94 SEP 30 AH 9: 00

APR 28 1995

For corners MMISSION

LAND CORNER RECORDATION CERTIFICATE

Washington

Cilin	D.m.		-4	A4	74	Minh	D.A	1070
ruing	nequ	irement	$\mathbf{o}_{\mathbf{I}}$	ACI	74.	MHCH.	P.A.	1970

. - 12/11/2011 PARTITION IN

	Macomb (County)	Located In: Township Corner Code ##	RECIST OF DEEDS MACOMB COUNTY, MT					
1.	Public Land Survey	T 4N R 12E H-7 T R	118FP 06464PG462					
2.	Property Controlling in Section	S T R						
3.	Miscellaneous Property in Sec.	\$TR	Register of Deeds Stamp & File Number					
	=	Recorded Plat	A B C D E F G H I J K L					

August 21 Huston K. Kennedy, in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1817-GLO Wampler, D.S.; Set Post; 12" Lynn S57°W 20 Links; 12" Lynn N45°W 21 Links

- 1.) 1976-Smith, P.S. #16052; LCRC L.2747, Pg.597 Fnd 3/4" Rod in a Monument Box
- 1990-Nelson, P.S. #21273; LCRC L.4816, Pg.948 Fnd 1/2" Pipe in a Monument Box
 1976-Smith, P.S. #16052; Survey L.2747, Pg.596 Fnd 3/4" Iron Rod in a Monument Box
- 4.) 1979-Kobs, P.S. #14097; Survey L.3074, Pg.519 Fnd 1/2" Pipe in a Monument Box 5.) 1992-King, P.S. #30085; Survey L.5778, Pg.395 Fnd 1/2" Iron Pipe in a Monument Box

	A	₿	C	D	Ē	F	G _	Н	<u>ا_</u> ا	K	Ļ	
2	_	6-		5	_	4	_	3	_	5		_
3	L	<u> </u>	↓	<u> </u>	<u>L</u>		L	<u> </u>	_			
4	L	-	}	8	<u>.</u>) 9	1	ļ 0	1	1	1	2
5	<u> </u>	<u> </u>	↓_	-	—	!	!	-	_	1		_
6	L	18	Ļ,	 7	۱.	 -	1	5	<u>_</u> 1	4	i	3—
7	_	ļ	╀	_	↓_	_	L	—				
8	L	19	 -;) 20	 _2) !1	-2	22	2	3	<u></u>	4—
9	L	-	↓_		<u> </u>	<u> </u>	<u> </u>	<u> </u>	_			
10	L,	 30	L.	 29	_2	 8	<u>L</u> 2	 !7	_2	6	2	5—
11	<u> </u>	1		L			L.		Ì			L.,
12		31—	Γ.	32_]_3	3	Ľ.	34	3	5	3	6—

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 1994 Kennedy Surveying, Inc. Kennedy, P.S. \$17623 Fnd 3/4" Iron Rod in a Monument Box in the centerline of 29 Mile Road, which has a bituminous surface, with a tree row extending to the North.

Witnesses from LCRC #1 & 3 were used to recover and verify the location of the found 3/4" Iron Rod in a Monument Box.

FIELD MEASUREMENT BETWEEN

H-7 to G-7 2638.86 Feet H-7 to I-7 2541.45 Feet ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD 9 4

MILLIAM E. SODERBERG, P.S., CHAIRMAN

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- H-7 I replaced the 3/4" Iron Rod in a Monument Box with a 3/4" x 24" Iron Rod w/2" diameter aluminum cap stamped "Macomb County Monument MI Act 345 #17623" in a existing Monument Box.

N72°E 156.70' Set PK & Remon. Washer South face Power Pole N73°W 125.56' Set PK & Remon. Washer South face Power Pole

NO6'W 34.97' Set PK & Remon. Washer East face 11" Walnut

N63 E 130.81' Set PK & Remon. Washer NW face 27" Elm

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

position of the original corner.

Signed by 17623 Surveyor's Michigan License No.

Date August

PROFESSIONAL CAND LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

ROFESSIONAL

REVISED JAN., 1983