SURVEY & REMONUMENTATION

APR 2 8 1995

For corners in

Property in Sec.

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Wachington

Macomb		, , , , , , , , , , , , , , , , , , ,	
		Located In: Townsh	ip Corner Code ≠
	(County)		
1.	Public Land Survey	T 4N R 12E	K-8
		T R	
		T R	
		T R	
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	S T R	
	Property in Sec.	S T R	

94 SEP 30 AM 9: 00 CARME.

C126154

REGIST ALGEDS MACOMA

HBER 06464PG467

Register of Deeds Stamp & File Number

Lot No, Recorded Plat			
Huston K. Kennedy, in a field survey on			

in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1817-GLO Wampler, D.S.; Set Post; 9" Ironwood S67°E 6 Links; 8" Ironwood N20°E 17 Links

- 1.) 1988-Avey, P.S. #15396; LCRC L.4353, Pg.439 Fnd "T" Bar bent, replaced with 1/2" Bar 2.) 1989-Avey, P.S. #15396; LCRC L.4584, Pg.239 Fnd 1/2" Bar, used same wit as 1988 LCRC 3.) 1989-Kobs, P.S. #14097; LCRC L.4729, Pg.131 Fnd 1/2" Iron

- 4.) 1975-Robs, P.S. #14097; Survey L.2590, Pg.321 Fnd "T" Iron 5.) 1987-Robs, P.S. #14097; Survey L.4220, Pg.474 Fnd "T" Iron, used same wit as 1975 Survey
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 1994 Kennedy Surveying, Inc. Kennedy, P.S. #17623 Fnd 1/2" Iron Rod in the centerline of Schoenherr Road, which has a gravel surface, and a tree row to the West 15' South of driveway for house #62000.

Witnesses from LCRC #1, 3 and Survey #4 were used to recover and verify the location of found 1/2" Iron Rod.

FIELD MEASUREMENT BETWEEN

K-8 to K-7 2541.70 Feet K-8 to K-9 2584.27 Feet ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD

10

11

12

WILLIAM E. SODERBERG, P.S., CHAIRMAN

KENNEDY

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- K-8 I replaced the 1/2" Iron Rod with a 3/4" x 24" Iron Rod w/2" diameter aluminum cap stamped "Macomb County Monument MI Act 345 #17623".

S17°E 149.43' Set PK & Remon. Washer SW face Power Pole

N32°E 63.07' Set PK & Remon. Washer NW face Power Pole

S42 W 45.88' Set PK & Remon. Washer NW face 19" Walnut

The selected location is accepted by me and is generally accepted by Professional Superprise as the best available evidence of the position of the original corner. position of the original corner.

Signed b)

Surveyor's Michigan License No.

Date .

17.7

COLONIA STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED JAN., 1983