LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

$\sim C120$	61	74	
94 SEP 30	AM	9: n:)
A .		*** ;	-

For Corners In			PERIOD LAUAUGH		
Macomb	Located In: Bruce Towns		REGISTAL DEEDS MACONE CONTY, MI		
Public Land Survey	T 4 N R 12 E T R T R T R	M-13	LIBER 06464 P.C487		
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R		Register of Deeds Stamp & File Number		
	Recorded Plat		- A B C D E F G H I J K L N		
do hereby certify that under re- in lines 1 and 2 above were in current manual of survey instr Management or by a decree of above were in conformance with Court of Law; established, expressed below: NOTE: Not more than 4 c	June quirements of P.A. 74, Michigan P.A. on conformance with regulations and ructions of the United States Departra Court of Law and/or that the corner ith the rules of the Michigan Board of re-established, monumented, re-micorners, all in the same town and	of 1970, the corner points mentioned if rules therefore as required in the ment of the Interior, Bureau of Land r points mentioned in lines 3, 4 and 6 f Land Surveyors or by a Decree of a nonumented, recovered, found as	6 18 17 16 15 14 13 14 15 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15		
on this certificate.			12 31 32 33 34 35 36		
A. Description of original	monument and accessories and	or subsequent restoration:			
1817-GLO Wampler, D.S.: Po	ist was made out of Ironwood 4" (diameter for Townshins 4 & 5. 1	Ranges 12 & 13 East: No hearing trees		

- 1.) 1979-Kobs, P.S. #14097; LCRC L.3162, Pg.598 Fnd 1/2" Pipe (Armada Twp.)
- 2.) 1980-Miller, P.S. #13589; LCRC L.3288, Pg.640 Fnd 3/8" Re-rod (Bruce Twp.)
 3.) 1989-Kobs, P.S. #14097; LCRC L.4729, Pg.131 Fnd 1/2" Iron Rod in a Monument Box (Washington Twp.)
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 1994 Kennedy Surveying, Inc. Kennedy, P.S. #17623 Fnd 5/8" Iron Rod in a Monument Box in the centerline of Powell Road, which has a concrete surface, and 21 feet North of the driveway for house #68950.

Witnesses from LCRC #2 & 3 were used to recover and verify the location of the found 5/8" Iron Rod in a Monument Box.

ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD WILLIAM E. SODERBERG, P.S., CHAIRMAN

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- M-13 I replaced the found 5/8" Iron Rod in a Monument Box with a 3/4" x 24" Iron Rod w/2" diameter aluminum cap stamped "Macomb County Monument HI Act 345 #17623" in a existing Monument Box.

S70°W 31.10' Set PK & Remon. Washer top of Guard Rail Post

S40 E 46.72' Set PK & Remon. Washer top of Guard Rail Post

S30 E 70.63' Set PK & Remon. Washer NE face Power Pole

N87 E 138.85' Set PK & Remon. Washer South face 36" Maple

white OF ME State of the The selected location is accepted by me and is generally accepted by Professional Surveyors as the position of the original corner.

Surveyor's Michigan License No.

17623

SHOFISSIONKS REVISED MAY 14, 1975 Walter Hill Hall Hall Hall

HUSTON KENNEDY OFESSION.

REVISED JAN., 1983