DEB 3 8 1233

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in MANISTEE (County)	Located In:	Corner Code #	REGISTER'S OFI MANISTEE COU! # 98: 338 AT	NTY 10:43 A.n.
Public Land Survey	T 21 N R 16 T 21 N R 15 T R		AUG 17 1998 Penny A. Roe REGISTER OF DE	na
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	T R S T R S T R S T R S T R S T R		Register of Deeds Stamp & F	ile Number
4. Lot No, F 5. Private Claims	Recorded Plat		1 A B C D E F G H	I J K L I
hereby certify that under recilines 1 and 2 above were current manual of survey ins Management or by a decree above were in conformance Court of Law; established expressed below:	quirements of P.A. 74, Michiga in conformance with regulation structions of the United States of a Court of Law and/or that with the rules of the Michigan d, re-established, monument 4 corners, all in the sa	eld survey on	ned in 4 7 8 9 10 10 11 12 31 32 33 34	23 24 26 25
A Description of origin	al monument and accessor	ries and/or subsequent restoration:	13	<u></u>
M - 2 East one-quarter co	orner section 1 T21N R14V	V & A - 2 West one-quarter corner s	ection 6 T21N R13W	
1837 GLO Survey by Joh Set post # 1 W. Pine 24" 830W 7 # 2 W Pine 13" N50 1/2 34.50 stream W. 40.0 (363 ft.)	' 1ks. 4.62 W 28 lks 18.48'	1967 K. Stephens Set 1" pipe # 3 W. Oak 23" N52W 19.55' # 4 W. Oak 6" N42E 14.04' # 5 C.C.C. post 8 28? 22.91'		

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- M 2 East one-quarter corner section 1 T21N R14W & A 2 West one-quarter corner section 6 T21N R13W

On July 10th 1998, I found the 1" pipe set by K. Stephens, in 1967, the condition of the witnesses is as follows

- # 1 Gone # 2 Gone # 3 Found # 4 Found # 5 Found, laying on ground
- Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- M 2 East one-quarter corner section 1 T21N R14W & A 2 West one-quarter corner section 6 T21N R13W

on July 10 I replaced the found 1" pipe with a standard Manistee County Monument stamped to identify the corner and took the following witnesses. This corner is accepted as a careful and faithful reestablishment of the position of the

# 3 W. Oak 26" N52W 19.57' set 60d spike in NE side
# 4 W. Oak 8" N42E 14.10' set 60d spike in SE side
# 6 Twin W. Oak 9" \$37W 34.22' set 60d spike in SE side
# 7 W. Oak 19" \$75E 43.72" set 60d spike in NE side

Corner is flush with the ground, and approximatley 400 ft North of Clay Bank Creek. Corner M-Q  $\frac{2}{2}$  fail

railfied by the Manistee County Peer Group according to the county plan adopted pursuant to P.A. 345 of 1990, as amended, (being the State Survey and Remonument/Act, MCL 54.261

et. seg.) Date of Peer Review:

Signed by Surveyor's Michigan License No. PS # 16923 Date 8/3

OF MICHIG SAMMY S. BARNETT PROFESSIONAL SURVEYOR No. 16923 POFESSION