MAY 1 6 1997

Surveyor's Michigan License No. 16923

For corners in

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MANI	STEE (County)	Located In:	Corner Code ##	REGISTER'S OFFICE MANISTEE COUNTY
1. Pu	blic Land Survey	T 22 N R 16 W	M-13 V	AUG 1 6 1996
		T DWR/SW	1	Comme Pegera
	pperty Controlling	S T R		REGISTER OF DEEDS
	Section scellaneous	S T R S T R		Denisher of Deads Stome 8 File Number
	perty in Sec.	S T R		Register of Deeds Stamp & File Number
	•			
				A B C D E F G H I J K L
5. Pri	vate Claims			2 6 5 4 4 3 2 2 1 1
				3
				4 7 - 1 8 - 1 9 - 1 1 1 1 1 2
ı, <u>Samm</u>	y S. Barnett	, in a field survey on <u>May</u>	<u>14</u> , 19 <u>96</u>	5
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the				6 18 17 16 15 14 13
current	manual of survey instru	ictions of the United States Depart	tment of the Interior, Bureau of Land	7
			er points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of a	8 19 20 21 22 23 24
			nonumented, recovered, found as	9
express	ed below:			10 30 29 28 27 26 25
NOTE:		orners, all in the same town ar	nd range, may be recorded	"
	on this certificate.			12 31 32 33 34 35 36
A. De	scription of original r	nonument and accessories and	d/or subsequent restoration:	13
M-13	Southeast Corner	for Section 36, T22N, R16W	, on the Township Line	
	3 0 1 407	* 0.1 0 1 1 =		
	Set Wood Post	, G.L.O., boundary survey	Don Skeels, 1908, MC	# . T. T. T
		" 530°W 71ks.(4.62')	Monument`not given #4 White Oak♪ 8" - S6!	261ks.(17.17')
		" N50½°W 281ks.(18.48')	#4 White Dak #8" 56	
	John Millard, 189	ga Mrs		Ken Stephens set 1" Iro
	Found Stake & Ye		E.W. Muencsher, 1914 Found Stake	, MCS #8 W. Oak 30" 570°E 5.
		S63°E 321ks.(21.12')	#6 Black Mak 12" S6	3½°E 311ks.(20.46') ing corner
B De	scription of corner ev	vidence found and/or method a	applied in restoring or reestablish	
M-13	Southeast Corner	for Section 36, T22N, R16W,	on the Township Line	#10 W.Oak 6" N80°W 29,
	On May 14, 1	996, I found a 1" Iron Pipe	, just above the surface of t	he ground, also found USFS tree tag
	witnessing this 1	ocation, stamped D. H. , Ma	rch, 1973, found CCC crusier	post S 78° E 34 feet, and the center-
	line of two-track	road lies 15 feet to the E	ast, I Compad no evidence to d	ispute this location for the Section
	roulet.		ուստուց տ աթ county p	Bill Adicated Dureward to D.A. DAG at Acco
	Condition of reco	rded witnesses are:	as amonaca, (Deing the Sill	e survey and Remonument Act, MCL 54.261
		•	et. seg.). Date of Peer Review	W:AUG 6 1996 Southon m. S.
	#1 Gone	#5 Gone	#9	Found in good Condition
	#2 Gone	#6 Same as 4		Found in good condition
	#3 Gone #4 Gone	#7 Same as 5		
C. Des			good condition established to perpetuate locating	the position of the corner
0. 00.	original or moridine.	a for comer and accessories e		the position of the conter.
M-13	Southeast Corner	for Section 36, T22N, R16W,	On the Township Line	
	I replaced 1"	Iron pipe , in the exact 1	ocation, with a Standard Manie	stee County Monument, set flush
	with the ground, a	and is accepted as a carefu	l and faithful reestablishment	of the position of the
				of the position of michigan
			spike in SE side of tree)	
	White Pi White or		(60d spike in SE side of tree)	SAMMY S. ** BARNETT
	•		Od spike in SW side of tree) Od spike in North side of trea	PROFESSIONAL P
	_	•		型

DEMOCE ILL 4081